
System Information

Time of this report: 10/25/2019, 08:58:15

Machine name: DESKTOP-EVUF8N1

Machine Id: {82AE2938-DBD9-4209-BDBA-D3A155D8051B}

Operating System: Windows 10 Home 64-bit (10.0, Build 18362) (18362.19h1_release.190318-1202)

Language: Italian (Regional Setting: Italian)

System Manufacturer: System manufacturer

System Model: System Product Name

BIOS: 1201 (type: UEFI)

Processor: AMD Ryzen 5 3600 6-Core Processor (12 CPUs), ~3.6GHz

Memory: 16384MB RAM

Available OS Memory: 16304MB RAM

Page File: 8692MB used, 10043MB available

Windows Dir: C:\Windows

DirectX Version: DirectX 12

DX Setup Parameters: Not found

User DPI Setting: 96 DPI (100 percent)

System DPI Setting: 96 DPI (100 percent)

DWM DPI Scaling: Disabled

Miracast: Available, with HDCP

Microsoft Graphics Hybrid: Not Supported

DirectX Database Version: Unknown

DxDiag Version: 10.00.18362.0387 64bit Unicode

DxDiag Notes

Display Tab 1: No problems found.

Sound Tab 1: No problems found.

Sound Tab 2: No problems found.

Input Tab: No problems found.

DirectX Debug Levels

Direct3D: 0/4 (retail)
DirectDraw: 0/4 (retail)
DirectInput: 0/5 (retail)
DirectMusic: 0/5 (retail)
DirectPlay: 0/9 (retail)
DirectSound: 0/5 (retail)
DirectShow: 0/6 (retail)

Display Devices

Card name: Radeon (TM) RX 480 Graphics
Manufacturer: Advanced Micro Devices, Inc.
Chip type: AMD Radeon Graphics Processor (0x67DF)
DAC type: Internal DAC(400MHz)
Device Type: Full Device (POST)
Device Key: Enum\PCI\VEN_1002&DEV_67DF&SUBSYS_94801682&REV_C7
Device Status: 0180200A
[DN_DRIVER_LOADED|DN_STARTED|DN_DISABLEABLE|DN_NT_ENUMERATOR|DN_NT_DRIVER]
Device Problem Code: No Problem
Driver Problem Code: Unknown
Display Memory: 16289 MB
Dedicated Memory: 8137 MB
Shared Memory: 8152 MB
Current Mode: 1920 x 1200 (32 bit) (60Hz)
HDR Support: Not Supported
Display Topology: Internal

Display Color Space: DXGI_COLOR_SPACE_RGB_FULL_G22_NONE_P709

Color Primaries: Red(0.639648,0.330078), Green(0.299805,0.599609), Blue(0.150391,0.059570), White Point(0.313477,0.329102)

Display Luminance: Min Luminance = 0.500000, Max Luminance = 270.000000, MaxFullFrameLuminance = 270.000000

Monitor Name: Generic PnP Monitor

Monitor Model: DELL U2412M

Monitor Id: DELA07B

Native Mode: 1920 x 1200(p) (59.950Hz)

Output Type: Displayport External

Monitor Capabilities: HDR Not Supported

Display Pixel Format: DISPLAYCONFIG_PIXELFORMAT_32BPP

Advanced Color: Not Supported

Driver Name:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\aticfx64.dll,C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\aticfx64.dll,C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\aticfx64.dll,C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\amdxc64.dll

Driver File Version: 26.20.13003.1007 (English)

Driver Version: 26.20.13003.1007

DDI Version: 12

Feature Levels: 12_0,11_1,11_0,10_1,10_0,9_3,9_2,9_1

Driver Model: WDDM 2.6

Graphics Preemption: Primitive

Compute Preemption: DMA

Miracast: Not Supported

Detachable GPU: No

Hybrid Graphics GPU: Not Supported

Power P-states: Not Supported

Virtualization: Paravirtualization

Block List: No Blocks

Catalog Attributes: Universal:False Declarative:True

Driver Attributes: Final Retail

Driver Date/Size: 10/09/2019 02:00:00, 1980960 bytes

WHQL Logo'd: Yes

WHQL Date Stamp: Unknown

Device Identifier: {D7B71EE2-249F-11CF-DD76-4B867CC2D735}

Vendor ID: 0x1002

Device ID: 0x67DF

SubSys ID: 0x94801682

Revision ID: 0x00C7

Driver Strong Name:

oem18.inf:cb0ae414b1258a48:ati2mtag_Polaris10:26.20.13003.1007:PCI\VEN_1002&DEV_67DF&REV_C7

Rank Of Driver: 00CF2000

Video Accel: Unknown

DXVA2 Modes: DXVA2_ModeMPEG2_VLD DXVA2_ModeMPEG2_IDCT
DXVA2_ModeH264_VLD_NoFGT DXVA2_ModeHEVC_VLD_Main
DXVA2_ModeH264_VLD_Stereo_Progressive_NoFGT DXVA2_ModeH264_VLD_Stereo_NoFGT
DXVA2_ModeVC1_VLD DXVA2_ModeMPEG4pt2_VLD_AdvSimple_NoGMC
DXVA2_ModeHEVC_VLD_Main10

Deinterlace Caps: n/a

D3D9 Overlay: Not Supported

DXVA-HD: Not Supported

DDraw Status: Enabled

D3D Status: Enabled

AGP Status: Enabled

MPO MaxPlanes: 1

MPO Caps: Not Supported

MPO Stretch: Not Supported

MPO Media Hints: Not Supported

MPO Formats: Not Supported

PanelFitter Caps: Not Supported

PanelFitter Stretch: Not Supported

Sound Devices

Description: Altoparlanti (Realtek(R) Audio)

Default Sound Playback: Yes

Default Voice Playback: Yes

Hardware ID: HDAUDIO\FUNC_01&VEN_10EC&DEV_1168&SUBSYS_10438733&REV_1001

Manufacturer ID: 1

Product ID: 100

Type: WDM

Driver Name: RTKVHD64.sys

Driver Version: 6.00.8816.0001 (English)

Driver Attributes: Final Retail

WHQL Logo'd: Yes

Date and Size: 15/10/2019 00:00:00, 7026264 bytes

Other Files:

Driver Provider: Realtek Semiconductor Corp.

HW Accel Level: Basic

Cap Flags: 0xF1F

Min/Max Sample Rate: 100, 200000

Static/Strm HW Mix Bufs: 1, 0

Static/Strm HW 3D Bufs: 0, 0

HW Memory: 0

Voice Management: No

EAX(tm) 2.0 Listen/Src: No, No

I3DL2(tm) Listen/Src: No, No

Sensaura(tm) ZoomFX(tm): No

Description: Realtek Digital Output (Realtek(R) Audio)

Default Sound Playback: No

Default Voice Playback: No

Hardware ID: HDAUDIO\FUNC_01&VEN_10EC&DEV_1168&SUBSYS_10438733&REV_1001

Manufacturer ID: 1

Product ID: 100

Type: WDM

Driver Name: RTKVHD64.sys

Driver Version: 6.00.8816.0001 (English)

Driver Attributes: Final Retail

WHQL Logo'd: Yes

Date and Size: 15/10/2019 00:00:00, 7026264 bytes

Other Files:

Driver Provider: Realtek Semiconductor Corp.

HW Accel Level: Basic

Cap Flags: 0xF1F

Min/Max Sample Rate: 100, 200000

Static/Strm HW Mix Bufs: 1, 0

Static/Strm HW 3D Bufs: 0, 0

HW Memory: 0

Voice Management: No

EAX(tm) 2.0 Listen/Src: No, No

I3DL2(tm) Listen/Src: No, No

Sensaura(tm) ZoomFX(tm): No

Sound Capture Devices

Video Capture Devices

Number of Devices: 0

DirectInput Devices

Device Name: Mouse

Attached: 1

Controller ID: n/a

Vendor/Product ID: n/a

FF Driver: n/a

Device Name: Tastiera

Attached: 1

Controller ID: n/a

Vendor/Product ID: n/a

FF Driver: n/a

Device Name: G400s Optical Gaming Mouse

Attached: 1

Controller ID: 0x0

Vendor/Product ID: 0x046D, 0xC24C

FF Driver: n/a

Device Name: USB Keyboard

Attached: 1

Controller ID: 0x0

Vendor/Product ID: 0x04D9, 0x2020

FF Driver: n/a

Device Name: USB Keyboard

Attached: 1

Controller ID: 0x0

Vendor/Product ID: 0x04D9, 0x2020

FF Driver: n/a

Device Name: UPS USB American Power Conversion

Attached: 1

Controller ID: 0x0

Vendor/Product ID: 0x051D, 0x0002

FF Driver: n/a

Device Name: AURA LED Controller

Attached: 1

Controller ID: 0x0

Vendor/Product ID: 0x0B05, 0x18F3

FF Driver: n/a

Poll w/ Interrupt: No

USB Devices

+ Hub radice USB (USB 3.0)

| Vendor/Product ID: 0x1022, 0x149C

| Matching Device ID: USB\ROOT_HUB30

| Service: USBHUB3

| Driver: USBHUB3.SYS, 3/19/2019 06:43:43, 618296 bytes

|

+--+ Dispositivo USB composito

| | Vendor/Product ID: 0x04D9, 0x2020

| | Location: Port_#0004.Hub_#0003

| | Matching Device ID: USB\COMPOSITE

| | Service: usbccgp

| | Driver: usbccgp.sys, 3/19/2019 06:43:43, 183608 bytes

| |

| +-+ Dispositivo di input USB

| | | Vendor/Product ID: 0x04D9, 0x2020

| | | Location: 000a.0000.0003.004.000.000.000.000

| | | Matching Device ID: USB\Class_03&SubClass_01

| | | Service: HidUsb

| | | Driver: hidusb.sys, 7/9/2019 03:50:12, 45568 bytes

| | | Driver: hidclass.sys, 7/9/2019 03:50:12, 211968 bytes

| | | Driver: hidparse.sys, 7/9/2019 03:50:12, 46080 bytes
| | |
| | +-+ Tastiera HID
| | | Vendor/Product ID: 0x04D9, 0x2020
| | | Matching Device ID: HID_DEVICE_SYSTEM_KEYBOARD
| | | Service: kbdhid
| | | Driver: kbdhid.sys, 3/19/2019 06:43:43, 46592 bytes
| | | Driver: kbdclass.sys, 3/19/2019 06:43:43, 70968 bytes
|
+ Hub radice USB (USB 3.0)
| Vendor/Product ID: 0x1022, 0x149C
| Matching Device ID: USB\ROOT_HUB30
| Service: USBHUB3
| Driver: USBHUB3.SYS, 3/19/2019 06:43:43, 618296 bytes
|
+-+ Dispositivo USB composito
| | Vendor/Product ID: 0x046D, 0xC24C
| | Location: Port_#0002.Hub_#0001
| | Matching Device ID: USB\COMPOSITE
| | Service: usbccgp
| | Driver: usbccgp.sys, 3/19/2019 06:43:43, 183608 bytes
| |
| +-+ Dispositivo di input USB
| | | Vendor/Product ID: 0x046D, 0xC24C
| | | Location: 0005.0000.0001.002.000.000.000.000
| | | Matching Device ID: USB\Class_03&SubClass_01
| | | Service: HidUsb
| | | Driver: hidusb.sys, 7/9/2019 03:50:12, 45568 bytes
| | | Driver: hidclass.sys, 7/9/2019 03:50:12, 211968 bytes
| | | Driver: hidparse.sys, 7/9/2019 03:50:12, 46080 bytes
| | |
| | +-+ Mouse compatibile HID

| | | Vendor/Product ID: 0x046D, 0xC24C
| | | Matching Device ID: HID_DEVICE_SYSTEM_MOUSE
| | | Service: mouhid
| | | Driver: mouhid.sys, 3/19/2019 06:43:43, 35840 bytes
| | | Driver: mouclass.sys, 3/19/2019 06:43:43, 66872 bytes

Gameport Devices

PS/2 Devices

Disk & DVD/CD-ROM Drives

Drive: C:

Free Space: 406.3 GB

Total Space: 476.3 GB

File System: NTFS

Model: Samsung SSD 970 EVO Plus 500GB

Drive: D:

Free Space: 203.0 GB

Total Space: 457.8 GB

File System: NTFS

Model: Crucial_CT480M500SSD1

Drive: E:

Free Space: 3353.5 GB

Total Space: 3815.4 GB

File System: NTFS

Model: WDC WD40EZRZ-00GXCB0

System Devices

Name: Controller AHCI SATA standard

Device ID: PCI\VEN_1022&DEV_7901&SUBSYS_79011022&REV_51\6&200D0A59&0&0048000A

Driver: C:\Windows\system32\DRIVERS\storahci.sys, 10.00.18362.0001 (English), 3/19/2019 06:43:41, 174392 bytes

Name: Adattatore PCI standard per CPU host

Device ID: PCI\VEN_1022&DEV_1447&SUBSYS_00000000&REV_00\3&11583659&0&C7

Driver: n/a

Name: Radeon (TM) RX 480 Graphics

Device ID: PCI\VEN_1002&DEV_67DF&SUBSYS_94801682&REV_C7\4&2F503515&0&0019

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\ati
esrxx.exe, 26.20.13003.1007 (English), 9/23/2019 13:25:08, 508008 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\ati
o6axx.dll, 26.20.13003.1007 (English), 9/23/2019 13:25:16, 43667048 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\ati
oglxx.dll, 26.20.13003.1007 (English), 9/23/2019 13:25:20, 35632744 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\ati
dxx32.dll, 26.20.13003.1007 (English), 9/23/2019 13:24:12, 23588648 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\ati
dxx64.dll, 26.20.13003.1007 (English), 9/23/2019 13:24:14, 28171696 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\ati
g6pxx.dll, 26.20.13003.1007 (English), 9/23/2019 13:25:10, 170088 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\atig6txx.dll, 26.20.13003.1007 (English), 9/23/2019 13:25:10, 242272 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\atigktxx.dll, 26.20.13003.1007 (English), 9/23/2019 13:25:12, 214120 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\atiglpxx.dll, 26.20.13003.1007 (English), 9/23/2019 13:25:12, 145512 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\atiu9p64.dll, 26.20.13003.1007 (English), 9/23/2019 13:24:16, 204400 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\atiu9pag.dll, 26.20.13003.1007 (English), 9/23/2019 13:24:16, 167568 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\atixp64.dll, 26.20.13003.1007 (English), 9/23/2019 13:24:20, 221080 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\atixpag.dll, 26.20.13003.1007 (English), 9/23/2019 13:24:22, 186752 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\aticfx32.dll, 26.20.13003.1007 (English), 9/23/2019 13:24:10, 1616136 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\aticfx64.dll, 26.20.13003.1007 (English), 9/23/2019 13:24:12, 1980960 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\amdocl.dll, 10.00.2906.0010 (English), 9/23/2019 13:24:44, 56516712 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\amdocl64.dll, 10.00.2906.0010 (English), 9/23/2019 13:24:48, 68489320 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\amdhd132.dll, 9/23/2019 13:24:02, 339728 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\amdhd164.dll, 9/23/2019 13:24:02, 423936 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\amd mantle32.dll, 26.20.13003.1007 (English), 9/23/2019 13:24:36, 22635624 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\amd mantle64.dll, 26.20.13003.1007 (English), 9/23/2019 13:24:38, 26707560 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\ati vce03.dat, 9/23/2019 12:39:54, 160768 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\ati vvaxy_vi.dat, 9/23/2019 12:39:56, 325188 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\ati vvaxy_vi_nd.dat, 9/23/2019 12:39:56, 324928 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\AMDh264Enc32.dll, 26.20.13003.1007 (English), 9/23/2019 13:23:58, 1467824 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\AMDh264Enc64.dll, 26.20.13003.1007 (English), 9/23/2019 13:24:00, 1682456 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\AMDhwDecoder_32.dll, 26.20.13003.1007 (English), 9/23/2019 13:24:32, 247400 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\AMDhwDecoder_64.dll, 26.20.13003.1007 (English), 9/23/2019 13:24:32, 300648 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\ati vvaxy_cz_nd.dat, 9/23/2019 12:39:54, 272544 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\am de31a.dat, 9/23/2019 12:39:26, 159072 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\ati vvaxy_FJ.dat, 9/23/2019 12:39:54, 268116 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\ati vvaxy_FJ_nd.dat, 9/23/2019 12:39:54, 267856 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\am dxc32.dll, 26.20.13003.1007 (English), 9/23/2019 13:24:06, 28235056 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\am dxc64.dll, 26.20.13003.1007 (English), 9/23/2019 13:24:08, 32720400 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\amdocl12cl.dll, 0.08.0000.0000 (English), 9/23/2019 13:24:46, 22169192 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\amdocl12cl64.dll, 0.08.0000.0000 (English), 9/23/2019 13:24:46, 27508840 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\amdicdxx.dat, 9/23/2019 12:39:28, 1078162 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\atidcdxx.dat, 9/23/2019 12:39:44, 737410 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\atidvaxy_el_nd.dat, 9/23/2019 12:39:54, 375456 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\amdvk32.dll, 26.20.13003.1007 (English), 9/23/2019 13:24:50, 37403240 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\amdvk64.dll, 26.20.13003.1007 (English), 9/23/2019 13:24:52, 41216616 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\amd-vulkan32.json, 9/23/2019 12:38:40, 703 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\amd-vulkan64.json, 9/23/2019 12:38:40, 703 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\amde34a.dat, 9/23/2019 12:39:26, 166624 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\atidvaxy_stn_nd.dat, 9/23/2019 12:39:54, 278176 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\ccc2_install.exe, 8.911.0003.3000 (English), 9/23/2019 13:25:24, 174698432 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\amde34b.dat, 9/23/2019 12:39:26, 166624 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\AMDh265Enc32.dll, 26.20.13003.1007 (English), 9/23/2019 13:24:00, 939560 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\AMDh265Enc64.dll, 26.20.13003.1007 (English), 9/23/2019 13:24:00, 1189944 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\amduve32.dll, 17.00.0006.0000 (English), 9/23/2019 13:24:04, 149128 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\amduve64.dll, 17.00.0006.0000 (English), 9/23/2019 13:24:06, 173608 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\amdmml.dll, 26.20.13003.1007 (English), 9/23/2019 13:24:42, 127080 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\amdmml6.dll, 26.20.13003.1007 (English), 9/23/2019 13:24:44, 149096 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\atiumd64.dll, 26.20.13003.1007 (English), 9/23/2019 13:24:18, 13507336 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\atiumd6a.dll, 26.20.13003.1007 (English), 9/23/2019 13:24:18, 13677792 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\atiumdag.dll, 26.20.13003.1007 (English), 9/23/2019 13:24:20, 10871336 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\atiumdva.dll, 26.20.13003.1007 (English), 9/23/2019 13:24:20, 13001392 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\ativce02.dat, 9/23/2019 12:39:54, 100832 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\ativvaxy_cik.dat, 9/23/2019 12:39:54, 234676 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\ativvaxy_cik_nd.dat, 9/23/2019 12:39:54, 234416 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\ativvaxy_gl_nd.dat, 9/23/2019 12:39:54, 378784 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\amide40a.dat, 9/23/2019 12:39:26, 173344 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\ativvaxy_rv.dat, 9/23/2019 12:39:54, 355008 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\amdave32.dll, 26.20.13003.1007 (English), 9/23/2019 13:23:58, 119232 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\amdave64.dll, 26.20.13003.1007 (English), 9/23/2019 13:23:58, 134832 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\ativvaxy_vg20.dat, 9/23/2019 12:39:56, 379200 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\ativvaxy_vg20_nd.dat, 9/23/2019 12:39:56, 381472 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\amdefctb.dat, 9/23/2019 12:39:26, 281096 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\amdxn32.dll, 8.14.0010.0026 (English), 9/23/2019 13:24:54, 28546664 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\amdxn64.dll, 8.14.0010.0026 (English), 9/23/2019 13:24:54, 32646248 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\atikmdag.sys, 26.20.13003.1007 (English), 9/23/2019 13:25:14, 60634216 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\atikmpag.sys, 26.20.13003.1007 (English), 9/23/2019 13:25:14, 597608 bytes

Driver:

C:\Windows\System32\DriverStore\FileRepository\u0346940.inf_amd64_1ea00c8019a8594e\B346681\ativvaxy_nv.dat, 9/23/2019 12:39:54, 457920 bytes

Driver: C:\Windows\system32\atieclxx.exe, 26.20.13003.1007 (English), 9/23/2019 13:25:08, 761440 bytes

Driver: C:\Windows\system32\atidemgy.dll, 4.05.7192.29820 (Italian), 9/23/2019 13:25:04, 468584 bytes

Driver: C:\Windows\system32\ati2erec.dll, 26.20.13003.1007 (English), 9/23/2019 13:25:00, 70248 bytes

Driver: C:\Windows\system32\atig6txx.dll, 26.20.13003.1007 (English), 9/23/2019 13:25:10, 242272 bytes

Driver: C:\Windows\system32\atiapfxx.blb, 9/23/2019 12:39:42, 552808 bytes

Driver: C:\Windows\system32\OpenCL.dll, 2.02.0001.0000 (English), 9/23/2019 13:24:56, 134752 bytes

Driver: C:\Windows\system32\clinfo.exe, 9/23/2019 13:25:24, 348776 bytes

Driver: C:\Windows\system32\kapp_ci.sbin, 9/23/2019 12:40:22, 125488 bytes

Driver: C:\Windows\system32\kapp_si.sbin, 9/23/2019 12:40:22, 121168 bytes

Driver: C:\Windows\system32\samu_krnl_ci.sbin, 9/2/2016 15:24:22, 154384 bytes

Driver: C:\Windows\system32\samu_krnl_isv_ci.sbin, 12/12/2013 13:53:56, 138832 bytes

Driver: C:\Windows\system32\mantle64.dll, 26.20.13003.1007 (English), 9/23/2019 13:25:34, 183912 bytes

Driver: C:\Windows\system32\mantleaxl64.dll, 26.20.13003.1007 (English), 9/23/2019 13:25:36, 162920 bytes

Driver: C:\Windows\system32\amf-mft-mjpeg-decoder64.dll, 26.20.13003.1007 (English), 9/23/2019 13:24:10, 1686000 bytes

Driver: C:\Windows\system32\mcl64.dll, 26.20.13003.1007 (English), 9/23/2019 13:25:36, 90728 bytes

Driver: C:\Windows\system32\amdgfxinfo64.dll, 9/23/2019 13:24:30, 472680 bytes

Driver: C:\Windows\system32\atieah64.exe, 9/23/2019 13:25:08, 439912 bytes

Driver: C:\Windows\system32\detoured.dll, 26.20.13003.1007 (English), 9/23/2019 13:25:26, 19768 bytes

Driver: C:\Windows\system32\Rapidfire64.dll, 1.02.0001.0286 (English), 9/23/2019 13:25:38, 574056 bytes

Driver: C:\Windows\system32\RapidFireServer64.dll, 1.02.0000.0015 (English), 9/23/2019 13:25:40, 46688 bytes

Driver: C:\Windows\system32\amdldr64.dll, 1.00.0016.0000 (English), 9/23/2019 13:24:36, 941160 bytes

Driver: C:\Windows\system32\vulkan-1.dll, 1.01.0114.0000 (English), 9/23/2019 13:25:42, 1072480 bytes

Driver: C:\Windows\system32\vulkan-1-999-0-0-0.dll, 1.01.0114.0000 (English), 9/23/2019 13:25:42, 1072480 bytes

Driver: C:\Windows\system32\vulkaninfo.exe, 1.01.0114.0000 (English), 9/23/2019 13:25:44, 851560 bytes

Driver: C:\Windows\system32\vulkaninfo-1-999-0-0-0.exe, 1.01.0114.0000 (English), 9/23/2019 13:25:44, 851560 bytes

Driver: C:\Windows\system32\GameManager64.dll, 9/23/2019 13:25:32, 480360 bytes

Driver: C:\Windows\system32\amdmiracast.dll, 9/23/2019 13:24:02, 554072 bytes

Driver: C:\Windows\system32\dgtrayicon.exe, 9/23/2019 13:25:28, 493160 bytes

Driver: C:\Windows\system32\AMDKernelEvents.man, 9/23/2019 12:39:28, 34488 bytes

Driver: C:\Windows\system32\amfrt64.dll, 1.04.0014.0000 (English), 9/23/2019 13:24:58, 3915368 bytes

Driver: C:\Windows\system32\amdmc164.dll, 1.06.0000.0000 (English), 9/23/2019 13:24:38, 553576 bytes

Driver: C:\Windows\system32\amdxc64.dll, 8.18.0010.0313 (English), 9/23/2019 13:24:52, 120936 bytes

Driver: C:\Windows\system32\aticfx64.dll, 8.17.0010.1669 (English), 9/23/2019 13:25:04, 178752 bytes

Driver: C:\Windows\system32\atidxx64.dll, 9/23/2019 13:25:06, 124008 bytes

Driver: C:\Windows\system32\atimpc64.dll, 26.20.13003.1007 (English), 9/23/2019 13:24:16, 128112 bytes

Driver: C:\Windows\system32\atimuixx.dll, 26.20.13003.1007 (English), 9/23/2019 13:25:16, 125544 bytes

Driver: C:\Windows\system32\atisamu64.dll, 26.20.13003.1007 (English), 9/23/2019 13:25:20, 158824 bytes

Driver: C:\Windows\system32\atiumd6a.cap, 9/23/2019 12:39:48, 3437632 bytes

Driver: C:\Windows\system32\ativsva.dat, 4/25/2017 00:55:26, 157144 bytes

Driver: C:\Windows\system32\ativsvl.dat, 4/25/2017 00:55:26, 204952 bytes

Driver: C:\Windows\system32\amdave64.dll, 26.20.13003.1007 (English), 9/23/2019 13:23:58, 134832 bytes

Driver: C:\Windows\system32\amdpcom64.dll, 26.20.13003.1007 (English), 9/23/2019 13:24:04, 128112 bytes

Driver: C:\Windows\system32\atiadlxx.dll, 26.20.13003.1007 (English), 9/23/2019 13:25:00, 1713768 bytes

Driver: C:\Windows\system32\EEURestart.exe, 9/23/2019 13:25:30, 416872 bytes

Driver: C:\Windows\system32\amdlogum.exe, 9/23/2019 13:24:34, 466536 bytes

Driver: C:\Windows\system32\amdhip64.dll, 10.00.2906.0010 (English), 9/23/2019 13:24:30, 68013672 bytes

Driver: C:\Windows\system32\amdcomgr64.dll, 9/23/2019 13:24:28, 59438696 bytes

Driver: C:\Windows\SysWOW64\atigktxx.dll, 26.20.13003.1007 (English), 9/23/2019 13:25:12, 214120 bytes

Driver: C:\Windows\SysWOW64\atiapfxx.blb, 9/23/2019 12:39:42, 552808 bytes

Driver: C:\Windows\SysWOW64\OpenCL.dll, 2.02.0001.0000 (English), 9/23/2019 13:24:56, 121440 bytes

Driver: C:\Windows\SysWOW64\mantle32.dll, 26.20.13003.1007 (English), 9/23/2019 13:25:32, 152680 bytes

Driver: C:\Windows\SysWOW64\mantleaxl32.dll, 26.20.13003.1007 (English), 9/23/2019 13:25:34, 138344 bytes

Driver: C:\Windows\SysWOW64\amf-mft-mjpeg-decoder32.dll, 26.20.13003.1007 (English), 9/23/2019 13:24:10, 1365360 bytes

Driver: C:\Windows\SysWOW64\mc132.dll, 26.20.13003.1007 (English), 9/23/2019 13:25:36, 75368 bytes

Driver: C:\Windows\SysWOW64\amdgfxinfo32.dll, 9/23/2019 13:24:30, 381544 bytes

Driver: C:\Windows\SysWOW64\atieah32.exe, 9/23/2019 13:25:06, 352360 bytes

Driver: C:\Windows\SysWOW64\detoured.dll, 26.20.13003.1007 (English), 9/23/2019 13:25:26, 19768 bytes

Driver: C:\Windows\SysWOW64\RapidFireServer.dll, 1.02.0000.0015 (English), 9/23/2019 13:25:40, 43624 bytes

Driver: C:\Windows\SysWOW64\Rapidfire.dll, 1.02.0001.0286 (English), 9/23/2019 13:25:38, 484968 bytes

Driver: C:\Windows\SysWOW64\amdldr32.dll, 1.00.0016.0000 (English), 9/23/2019 13:24:36, 768616 bytes

Driver: C:\Windows\SysWOW64\vulkan-1.dll, 1.01.0114.0000 (English), 9/23/2019 13:25:40, 929280 bytes

Driver: C:\Windows\SysWOW64\vulkan-1-999-0-0-0.dll, 1.01.0114.0000 (English), 9/23/2019 13:25:40, 929280 bytes

Driver: C:\Windows\SysWOW64\vulkaninfo.exe, 1.01.0114.0000 (English), 9/23/2019 13:25:42, 709224 bytes

Driver: C:\Windows\SysWOW64\vulkaninfo-1-999-0-0-0.exe, 1.01.0114.0000 (English), 9/23/2019 13:25:42, 709224 bytes

Driver: C:\Windows\SysWOW64\GameManager32.dll, 9/23/2019 13:25:30, 381544 bytes

Driver: C:\Windows\SysWOW64\amfrt32.dll, 1.04.0014.0000 (English), 9/23/2019 13:24:58, 3516520 bytes

Driver: C:\Windows\SysWOW64\amdmc132.dll, 1.06.0000.0000 (English), 9/23/2019 13:24:38, 383592 bytes

Driver: C:\Windows\SysWOW64\amdxc32.dll, 8.18.0010.0313 (English), 9/23/2019 13:24:52, 105576 bytes

Driver: C:\Windows\SysWOW64\aticfx32.dll, 8.17.0010.1669 (English), 9/23/2019 13:25:02, 157592 bytes

Driver: C:\Windows\SysWOW64\atidxx32.dll, 9/23/2019 13:25:04, 107104 bytes

Driver: C:\Windows\SysWOW64\atimpc32.dll, 26.20.13003.1007 (English), 9/23/2019 13:24:14, 107728 bytes

Driver: C:\Windows\SysWOW64\atisamu32.dll, 26.20.13003.1007 (English), 9/23/2019 13:25:20, 135784 bytes

Driver: C:\Windows\SysWOW64\atiumdva.cap, 9/23/2019 12:39:54, 3471376 bytes

Driver: C:\Windows\SysWOW64\ativvsva.dat, 4/25/2017 00:55:26, 157144 bytes

Driver: C:\Windows\SysWOW64\ativvsvl.dat, 4/25/2017 00:55:26, 204952 bytes

Driver: C:\Windows\SysWOW64\amdave32.dll, 26.20.13003.1007 (English), 9/23/2019 13:23:58, 119232 bytes

Driver: C:\Windows\SysWOW64\amdpcom32.dll, 26.20.13003.1007 (English), 9/23/2019 13:24:04, 107728 bytes

Driver: C:\Windows\SysWOW64\atiadlxx.dll, 26.20.13003.1007 (English), 9/23/2019 13:25:02, 1242728 bytes

Driver: C:\Windows\SysWOW64\atiadlxy.dll, 26.20.13003.1007 (English), 9/23/2019 13:25:02, 1242728 bytes

Driver: C:\Windows\SysWOW64\amdcomgr.dll, 9/23/2019 13:24:28, 49335400 bytes

Driver: C:\Windows\system32\AMD\amdkmpfd\amdkmpfd.stz, 19.20.0001.0000 (English), 9/23/2019 13:24:34, 102832 bytes

Driver: C:\Windows\system32\AMD\amdkmpfd\amdkmpfd.itz, 9/23/2019 12:39:28, 1999 bytes

Driver: C:\Windows\system32\AMD\amdkmpfd\amdkmpfd.ctz, 9/23/2019 12:39:28, 8590 bytes

Name: Porta di commutazione downstream PCI Express

Device ID: PCI\VEN_1022&DEV_57A4&SUBSYS_14841022&REV_00\5&26478365&0&48000A

Driver: C:\Windows\system32\DRIVERS\pci.sys, 10.00.18362.0418 (Italian), 10/8/2019 19:54:20, 436536 bytes

Name: Controller host AMD USB 3.10 eXtensible - 1.10 (Microsoft)

Device ID: PCI\VEN_1022&DEV_149C&SUBSYS_87C01043&REV_00\6&6A77C41&0&0140000A

Driver: C:\Windows\system32\DRIVERS\USBXHCI.SYS, 10.00.18362.0207 (Italian), 7/9/2019 03:50:12, 531976 bytes

Driver: C:\Windows\system32\DRIVERS\UMDF\UsbXhciCompanion.dll, 10.00.18362.0207 (English), 7/9/2019 03:50:12, 131960 bytes

Name: Porta di commutazione downstream PCI Express

Device ID: PCI\VEN_1022&DEV_57A4&SUBSYS_14841022&REV_00\5&26478365&0&50000A

Driver: C:\Windows\system32\DRIVERS\pci.sys, 10.00.18362.0418 (Italian), 10/8/2019 19:54:20, 436536 bytes

Name: Adattatore PCI standard per CPU host

Device ID: PCI\VEN_1022&DEV_1442&SUBSYS_00000000&REV_00\3&11583659&0&C2

Driver: n/a

Name: Controller host AMD USB 3.10 eXtensible - 1.10 (Microsoft)

Device ID: PCI\VEN_1022&DEV_149C&SUBSYS_148C1022&REV_00\6&6A77C41&0&0340000A

Driver: C:\Windows\system32\DRIVERS\USBXHCI.SYS, 10.00.18362.0207 (Italian), 7/9/2019 03:50:12, 531976 bytes

Driver: C:\Windows\system32\DRIVERS\UMDF\UsbXhciCompanion.dll, 10.00.18362.0207 (English), 7/9/2019 03:50:12, 131960 bytes

Name: Porta di commutazione downstream PCI Express

Device ID: PCI\VEN_1022&DEV_57A3&SUBSYS_87C01043&REV_00\000C8700000000128

Driver: C:\Windows\system32\DRIVERS\pci.sys, 10.00.18362.0418 (Italian), 10/8/2019 19:54:20, 436536 bytes

Name: Porta di commutazione downstream PCI Express

Device ID: PCI\VEN_1022&DEV_57A3&SUBSYS_87C01043&REV_00\000C8700000000108

Driver: C:\Windows\system32\DRIVERS\pci.sys, 10.00.18362.0418 (Italian), 10/8/2019 19:54:20, 436536 bytes

Name: AMD PCI

Device ID: PCI\VEN_1022&DEV_1485&SUBSYS_87C01043&REV_00\6&6A77C41&0&0040000A

Driver: C:\Windows\system32\DRIVERS\AMDPCIDev.sys, 1.00.0000.0074 (English), 9/16/2019 16:47:20, 32520 bytes

Name: Porta di commutazione downstream PCI Express

Device ID: PCI\VEN_1022&DEV_57A4&SUBSYS_14841022&REV_00\5&26478365&0&40000A

Driver: C:\Windows\system32\DRIVERS\pci.sys, 10.00.18362.0418 (Italian), 10/8/2019 19:54:20, 436536 bytes

Name: Adattatore PCI standard per CPU host

Device ID: PCI\VEN_1022&DEV_1445&SUBSYS_00000000&REV_00\3&11583659&0&C5

Driver: n/a

Name: AMD PCI

Device ID: PCI\VEN_1022&DEV_1485&SUBSYS_87C01043&REV_00\4&1FDE7688&0&0041

Driver: C:\Windows\system32\DRIVERS\AMDPCIDev.sys, 1.00.0000.0074 (English), 9/16/2019 16:47:20, 32520 bytes

Name: Adattatore PCI standard per CPU host

Device ID: PCI\VEN_1022&DEV_1440&SUBSYS_00000000&REV_00\3&11583659&0&C0

Driver: n/a

Name: Adattatore PCI standard per CPU host

Device ID: PCI\VEN_1022&DEV_1482&SUBSYS_00000000&REV_00\3&11583659&0&40

Driver: n/a

Name: Adattatore PCI standard per CPU host

Device ID: PCI\VEN_1022&DEV_1482&SUBSYS_00000000&REV_00\3&11583659&0&38

Driver: n/a

Name: Adattatore PCI standard per CPU host

Device ID: PCI\VEN_1022&DEV_1482&SUBSYS_00000000&REV_00\3&11583659&0&28

Driver: n/a

Name: Adattatore PCI standard per CPU host

Device ID: PCI\VEN_1022&DEV_1482&SUBSYS_00000000&REV_00\3&11583659&0&20

Driver: n/a

Name: Adattatore PCI standard per CPU host

Device ID: PCI\VEN_1022&DEV_1482&SUBSYS_00000000&REV_00\3&11583659&0&18

Driver: n/a

Name: Adattatore PCI standard per CPU host

Device ID: PCI\VEN_1022&DEV_1482&SUBSYS_00000000&REV_00\3&11583659&0&10

Driver: n/a

Name: Adattatore PCI standard per CPU host

Device ID: PCI\VEN_1022&DEV_1482&SUBSYS_00000000&REV_00\3&11583659&0&08

Driver: n/a

Name: Adattatore PCI standard per CPU host

Device ID: PCI\VEN_1022&DEV_1443&SUBSYS_00000000&REV_00\3&11583659&0&C3

Driver: n/a

Name: Controller AHCI SATA standard

Device ID: PCI\VEN_1022&DEV_7901&SUBSYS_87C01043&REV_51\4&3298272D&0&0042

Driver: C:\Windows\system32\DRIVERS\storahci.sys, 10.00.18362.0001 (English), 3/19/2019 06:43:41, 174392 bytes

Name: AMD PCI

Device ID: PCI\VEN_1022&DEV_148A&SUBSYS_87C01043&REV_00\4&D573D7&0&0039

Driver: C:\Windows\system32\DRIVERS\AMDPCIDev.sys, 1.00.0000.0074 (English), 9/16/2019 16:47:20, 32520 bytes

Name: Controller AHCI SATA standard

Device ID: PCI\VEN_1022&DEV_7901&SUBSYS_79011022&REV_51\6&3825506&0&0050000A

Driver: C:\Windows\system32\DRIVERS\storahci.sys, 10.00.18362.0001 (English), 3/19/2019 06:43:41, 174392 bytes

Name: AMD SMBus

Device ID: PCI\VEN_1022&DEV_790B&SUBSYS_87C01043&REV_61\3&11583659&0&A0

Driver: n/a

Name: Adattatore PCI standard per CPU host

Device ID: PCI\VEN_1022&DEV_1446&SUBSYS_00000000&REV_00\3&11583659&0&C6

Driver: n/a

Name: Adattatore PCI standard per CPU host

Device ID: PCI\VEN_1022&DEV_1480&SUBSYS_87C01043&REV_00\3&11583659&0&00

Driver: n/a

Name: AMD PSP 11.0 Device

Device ID: PCI\VEN_1022&DEV_1486&SUBSYS_87C01043&REV_00\4&1FDE7688&0&0141

Driver: C:\Windows\system32\DRIVERS\amdpsp.sys, 4.11.0000.0000 (English), 6/26/2019 22:44:58, 138064 bytes

Driver: C:\Windows\system32\amdtee_api.dll, 4.11.0000.0000 (English), 6/26/2019 22:44:58, 429688 bytes

Driver: C:\Windows\SysWOW64\amdtee_api.dll, 4.11.0000.0000 (English), 6/26/2019 22:44:58, 341624 bytes

Name: Porta radice PCI Express

Device ID: PCI\VEN_1022&DEV_1484&SUBSYS_14841022&REV_00\3&11583659&0&43

Driver: C:\Windows\system32\DRIVERS\pci.sys, 10.00.18362.0418 (Italian), 10/8/2019 19:54:20, 436536 bytes

Name: Porta radice PCI Express

Device ID: PCI\VEN_1022&DEV_1484&SUBSYS_14841022&REV_00\3&11583659&0&42

Driver: C:\Windows\system32\DRIVERS\pci.sys, 10.00.18362.0418 (Italian), 10/8/2019 19:54:20, 436536 bytes

Name: Porta radice PCI Express

Device ID: PCI\VEN_1022&DEV_1484&SUBSYS_14841022&REV_00\3&11583659&0&41

Driver: C:\Windows\system32\DRIVERS\pci.sys, 10.00.18362.0418 (Italian), 10/8/2019 19:54:20, 436536 bytes

Name: Porta radice PCI Express

Device ID: PCI\VEN_1022&DEV_1484&SUBSYS_14841022&REV_00\3&11583659&0&39

Driver: C:\Windows\system32\DRIVERS\pci.sys, 10.00.18362.0418 (Italian), 10/8/2019 19:54:20, 436536 bytes

Name: Controller per High Definition Audio

Device ID: PCI\VEN_1002&DEV_AAF0&SUBSYS_AAF01682&REV_00\4&2F503515&0&0119

Driver: C:\Windows\system32\DRIVERS\hdaudbus.sys, 10.00.18362.0001 (English), 3/19/2019 06:43:37, 114688 bytes

Driver: C:\Windows\system32\DRIVERS\drmks.sys, 10.00.18362.0001 (English), 3/19/2019 06:43:37, 98304 bytes

Driver: C:\Windows\system32\DRIVERS\portcls.sys, 10.00.18362.0001 (English), 3/19/2019 06:43:37, 390656 bytes

Name: Porta di commutazione upstream PCI Express

Device ID: PCI\VEN_1022&DEV_57AD&SUBSYS_00000000&REV_00\4&10473264&0&000A

Driver: C:\Windows\system32\DRIVERS\pci.sys, 10.00.18362.0418 (Italian), 10/8/2019 19:54:20, 436536 bytes

Name: Controller host AMD USB 3.10 eXtensible - 1.10 (Microsoft)

Device ID: PCI\VEN_1022&DEV_149C&SUBSYS_87C01043&REV_00\4&1FDE7688&0&0341

Driver: C:\Windows\system32\DRIVERS\USBXHCI.SYS, 10.00.18362.0207 (Italian), 7/9/2019 03:50:12, 531976 bytes

Driver: C:\Windows\system32\DRIVERS\UMDF\UsbXhciCompanion.dll, 10.00.18362.0207 (English), 7/9/2019 03:50:12, 131960 bytes

Name: Intel(R) I211 Gigabit Network Connection

Device ID: PCI\VEN_8086&DEV_1539&SUBSYS_85F01043&REV_03\04D9F5FFFF7C011A00

Driver: C:\Windows\system32\DRIVERS\e1r68x64.sys, 12.18.0008.0022 (Italian), 5/20/2019 18:45:14, 592240 bytes

Driver: C:\Windows\system32\e1r68x64.din, 5/20/2019 18:45:14, 3096 bytes

Driver: C:\Windows\system32\e1rmsg.dll, 10.00.0866.0000 (English), 5/20/2019 18:45:14, 92016 bytes

Name: Adattatore PCI standard per bus ISA

Device ID: PCI\VEN_1022&DEV_790E&SUBSYS_87C01043&REV_51\3&11583659&0&A3

Driver: C:\Windows\system32\DRIVERS\msisadrv.sys, 10.00.18362.0267 (English), 9/10/2019 23:40:33, 19256 bytes

Name: Controller AHCI SATA standard

Device ID: PCI\VEN_1022&DEV_7901&SUBSYS_87C01043&REV_51\4&9B70DCB&0&0043

Driver: C:\Windows\system32\DRIVERS\storahci.sys, 10.00.18362.0001 (English), 3/19/2019 06:43:41, 174392 bytes

Name: Porta radice PCI Express

Device ID: PCI\VEN_1022&DEV_1483&SUBSYS_87C01043&REV_00\000C8700000000119

Driver: C:\Windows\system32\DRIVERS\pci.sys, 10.00.18362.0418 (Italian), 10/8/2019 19:54:20, 436536 bytes

Name: Porta radice PCI Express

Device ID: PCI\VEN_1022&DEV_1483&SUBSYS_87C01043&REV_00\000C8700000000010A

Driver: C:\Windows\system32\DRIVERS\pci.sys, 10.00.18362.0418 (Italian), 10/8/2019 19:54:20, 436536 bytes

Name: Adattatore PCI standard per CPU host

Device ID: PCI\VEN_1022&DEV_1441&SUBSYS_00000000&REV_00\3&11583659&0&C1

Driver: n/a

Name: Controller per High Definition Audio

Device ID: PCI\VEN_1022&DEV_1487&SUBSYS_87331043&REV_00\4&1FDE7688&0&0441

Driver: C:\Windows\system32\DRIVERS\hdaudbus.sys, 10.00.18362.0001 (English), 3/19/2019 06:43:37, 114688 bytes

Driver: C:\Windows\system32\DRIVERS\drmks.sys, 10.00.18362.0001 (English), 3/19/2019 06:43:37, 98304 bytes

Driver: C:\Windows\system32\DRIVERS\portcls.sys, 10.00.18362.0001 (English), 3/19/2019 06:43:37, 390656 bytes

Name: Adattatore PCI standard per CPU host

Device ID: PCI\VEN_1022&DEV_1444&SUBSYS_00000000&REV_00\3&11583659&0&C4

Driver: n/a

Name: Samsung NVMe Controller

Device ID: PCI\VEN_144D&DEV_A808&SUBSYS_A801144D&REV_00\6&1DD712BF&0&0008000A

Driver: C:\Windows\system32\DRIVERS\secnvme.sys, 3.01.0000.1901 (English), 1/21/2019 10:57:18, 134000 bytes

DirectShow Filters

DirectShow Filters:

WMAudio Decoder DMO,0x00800800,1,1,WMADMOD.DLL,10.00.18362.0145
WMAPro over S/PDIF DMO,0x00600800,1,1,WMADMOD.DLL,10.00.18362.0145
WMSpeech Decoder DMO,0x00600800,1,1,WMSPDMOD.DLL,10.00.18362.0001
MP3 Decoder DMO,0x00600800,1,1,mp3dmod.dll,10.00.18362.0001
Mpeg4s Decoder DMO,0x00800001,1,1,mp4sdecdec.dll,10.00.18362.0001
WMV Screen decoder DMO,0x00600800,1,1,wmvsdecdec.dll,10.00.18362.0001
WMVideo Decoder DMO,0x00800001,1,1,wmvdecdec.dll,10.00.18362.0001
Mpeg43 Decoder DMO,0x00800001,1,1,mp43decdec.dll,10.00.18362.0001
Mpeg4 Decoder DMO,0x00800001,1,1,mpg4decdec.dll,10.00.18362.0001
DV Muxer,0x00400000,0,0,qdv.dll,10.00.18362.0001
Color Space Converter,0x00400001,1,1,quartz.dll,10.00.18362.0001
WM ASF Reader,0x00400000,0,0,qasf.dll,12.00.18362.0001
AVI Splitter,0x00600000,1,1,quartz.dll,10.00.18362.0001
VGA 16 Color Ditherer,0x00400000,1,1,quartz.dll,10.00.18362.0001
SBE2MediaTypeProfile,0x00200000,0,0,sbe.dll,10.00.18362.0001
Microsoft DTV-DVD Video Decoder,0x005fffff,2,4,msmpeg2vdec.dll,10.00.18362.0418
AC3 Parser Filter,0x00600000,1,1,mpg2splnt.ax,10.00.18362.0001
StreamBufferSink,0x00200000,0,0,sbe.dll,10.00.18362.0001
MJPEG Decompressor,0x00600000,1,1,quartz.dll,10.00.18362.0001
MPEG-I Stream Splitter,0x00600000,1,2,quartz.dll,10.00.18362.0001
SAMI (CC) Parser,0x00400000,1,1,quartz.dll,10.00.18362.0001
VBI Codec,0x00600000,1,4,VBICodec.ax,10.00.18362.0001
MPEG-2 Splitter,0x005fffff,1,0,mpg2splnt.ax,10.00.18362.0001
Closed Captions Analysis Filter,0x00200000,2,5,cca.dll,10.00.18362.0001
SBE2FileScan,0x00200000,0,0,sbe.dll,10.00.18362.0001
Microsoft MPEG-2 Video Encoder,0x00200000,1,1,msmpeg2enc.dll,10.00.18362.0001
Internal Script Command Renderer,0x00800001,1,0,quartz.dll,10.00.18362.0001
MPEG Audio Decoder,0x03680001,1,1,quartz.dll,10.00.18362.0001
DV Splitter,0x00600000,1,2,qdv.dll,10.00.18362.0001
Video Mixing Renderer 9,0x00200000,1,0,quartz.dll,10.00.18362.0001
Microsoft MPEG-2 Encoder,0x00200000,2,1,msmpeg2enc.dll,10.00.18362.0001
ACM Wrapper,0x00600000,1,1,quartz.dll,10.00.18362.0001

Video Renderer,0x00800001,1,0,quartz.dll,10.00.18362.0001
MPEG-2 Video Stream Analyzer,0x00200000,0,0,sbe.dll,10.00.18362.0001
Line 21 Decoder,0x00600000,1,1,,
Video Port Manager,0x00600000,2,1,quartz.dll,10.00.18362.0001
Video Renderer,0x00400000,1,0,quartz.dll,10.00.18362.0001
VPS Decoder,0x00200000,0,0,WSTPager.ax,10.00.18362.0001
WM ASF Writer,0x00400000,0,0,qasf.dll,12.00.18362.0001
VBI Surface Allocator,0x00600000,1,1,vbisurf.ax,
File writer,0x00200000,1,0,qcap.dll,10.00.18362.0001
DVD Navigator,0x00200000,0,3,qdvd.dll,10.00.18362.0001
Overlay Mixer2,0x00200000,1,1,,
AVI Draw,0x00600064,9,1,quartz.dll,10.00.18362.0001
Microsoft MPEG-2 Audio Encoder,0x00200000,1,1,msmpeg2enc.dll,10.00.18362.0001
WST Pager,0x00200000,1,1,WSTPager.ax,10.00.18362.0001
MPEG-2 Demultiplexer,0x00600000,1,1,mpg2spl.t.ax,10.00.18362.0001
DV Video Decoder,0x00800000,1,1,qdv.dll,10.00.18362.0001
SampleGrabber,0x00200000,1,1,qedit.dll,10.00.18362.0001
Null Renderer,0x00200000,1,0,qedit.dll,10.00.18362.0001
MPEG-2 Sections and Tables,0x005fffff,1,0,Mpeg2Data.ax,10.00.18362.0001
Microsoft AC3 Encoder,0x00200000,1,1,msac3enc.dll,10.00.18362.0001
StreamBufferSource,0x00200000,0,0,sbe.dll,10.00.18362.0001
Smart Tee,0x00200000,1,2,qcap.dll,10.00.18362.0001
Overlay Mixer,0x00200000,0,0,,
AVI Decompressor,0x00600000,1,1,quartz.dll,10.00.18362.0001
AVI/WAV File Source,0x00400000,0,2,quartz.dll,10.00.18362.0001
Wave Parser,0x00400000,1,1,quartz.dll,10.00.18362.0001
MIDI Parser,0x00400000,1,1,quartz.dll,10.00.18362.0001
Multi-file Parser,0x00400000,1,1,quartz.dll,10.00.18362.0001
File stream renderer,0x00400000,1,1,quartz.dll,10.00.18362.0001
Microsoft DTV-DVD Audio Decoder,0x005fffff,1,1,msmpeg2adec.dll,10.00.18362.0001
StreamBufferSink2,0x00200000,0,0,sbe.dll,10.00.18362.0001
AVI Mux,0x00200000,1,0,qcap.dll,10.00.18362.0001

Line 21 Decoder 2,0x00600002,1,1,quartz.dll,10.00.18362.0001
File Source (Async.),0x00400000,0,1,quartz.dll,10.00.18362.0001
File Source (URL),0x00400000,0,1,quartz.dll,10.00.18362.0001
Infinite Pin Tee Filter,0x00200000,1,1,qcap.dll,10.00.18362.0001
Enhanced Video Renderer,0x00200000,1,0,evr.dll,10.00.18362.0001
BDA MPEG2 Transport Information Filter,0x00200000,2,0,psisrndr.ax,10.00.18362.0001
MPEG Video Decoder,0x40000001,1,1,quartz.dll,10.00.18362.0001

WDM Streaming Tee/Splitter Devices:

Convertitore a T/Sito a sito,0x00200000,1,1,ksproxy.ax,10.00.18362.0001

Video Compressors:

WMVideo8 Encoder DMO,0x00600800,1,1,wmvxencd.dll,10.00.18362.0001
WMVideo9 Encoder DMO,0x00600800,1,1,wmvencod.dll,10.00.18362.0001
MSScreen 9 encoder DMO,0x00600800,1,1,wmvsencd.dll,10.00.18362.0001
DV Video Encoder,0x00200000,0,0,qdv.dll,10.00.18362.0001
MJPEG Compressor,0x00200000,0,0,quartz.dll,10.00.18362.0001

Audio Compressors:

WM Speech Encoder DMO,0x00600800,1,1,WMSPDMOE.DLL,10.00.18362.0145
WMAudio Encoder DMO,0x00600800,1,1,WMADMOE.DLL,10.00.18362.0145
IMA ADPCM,0x00200000,1,1,quartz.dll,10.00.18362.0001
PCM,0x00200000,1,1,quartz.dll,10.00.18362.0001
Microsoft ADPCM,0x00200000,1,1,quartz.dll,10.00.18362.0001
GSM 6.10,0x00200000,1,1,quartz.dll,10.00.18362.0001
CCITT A-Law,0x00200000,1,1,quartz.dll,10.00.18362.0001
CCITT u-Law,0x00200000,1,1,quartz.dll,10.00.18362.0001
MPEG Layer-3,0x00200000,1,1,quartz.dll,10.00.18362.0001

PBDA CP Filters:

PBDA DTFilter,0x00600000,1,1,CPFilters.dll,10.00.18362.0418
PBDA ETFilter,0x00200000,0,0,CPFilters.dll,10.00.18362.0418

PBDA PTFilter,0x00200000,0,0,CPFilters.dll,10.00.18362.0418

Midi Renderers:

Default MidiOut Device,0x00800000,1,0,quartz.dll,10.00.18362.0001

Microsoft GS Wavetable Synth,0x00200000,1,0,quartz.dll,10.00.18362.0001

WDM Streaming Capture Devices:

Realtek HD Audio Stereo input,0x00200000,1,1,ksproxy.ax,10.00.18362.0001

Realtek HD Audio Line input,0x00200000,1,1,ksproxy.ax,10.00.18362.0001

Realtek HD Audio Mic input,0x00200000,1,1,ksproxy.ax,10.00.18362.0001

WDM Streaming Rendering Devices:

Realtek HD Audio output,0x00200000,1,1,ksproxy.ax,10.00.18362.0001

Realtek HDA SPDIF Out,0x00200000,1,1,ksproxy.ax,10.00.18362.0001

BDA Network Providers:

Microsoft ATSC Network Provider,0x00200000,0,1,MSDvbNP.ax,10.00.18362.0001

Microsoft DVBC Network Provider,0x00200000,0,1,MSDvbNP.ax,10.00.18362.0001

Microsoft DVBS Network Provider,0x00200000,0,1,MSDvbNP.ax,10.00.18362.0001

Microsoft DVBT Network Provider,0x00200000,0,1,MSDvbNP.ax,10.00.18362.0001

Microsoft Network Provider,0x00200000,0,1,MSNP.ax,10.00.18362.0001

Multi-Instance Capable VBI Codecs:

VBI Codec,0x00600000,1,4,VBICodec.ax,10.00.18362.0001

BDA Transport Information Renderers:

BDA MPEG2 Transport Information Filter,0x00600000,2,0,psisrndr.ax,10.00.18362.0001

MPEG-2 Sections and Tables,0x00600000,1,0,Mpeg2Data.ax,10.00.18362.0001

WDM Streaming Communication Transforms:

Convertitore a T/Sito a sito,0x00200000,1,1,ksproxy.ax,10.00.18362.0001

Audio Renderers:

Altoparlanti (Realtek(R) Audio),0x00200000,1,0,quartz.dll,10.00.18362.0001

Default DirectSound Device,0x00800000,1,0,quartz.dll,10.00.18362.0001

Default WaveOut Device,0x00200000,1,0,quartz.dll,10.00.18362.0001

DirectSound: Altoparlanti (Realtek(R) Audio),0x00200000,1,0,quartz.dll,10.00.18362.0001

DirectSound: Realtek Digital Output (Realtek(R) Audio),0x00200000,1,0,quartz.dll,10.00.18362.0001

Realtek Digital Output (Realtek(R) Audio),0x00200000,1,0,quartz.dll,10.00.18362.0001

Preferred DirectShow Filters

[HKEY_LOCAL_MACHINE\Software\Microsoft\DirectShow\Preferred]

<media subtype GUID>, [<filter friendly name>,]<filter CLSID>

MEDIASUBTYPE_DVD_LPCM_AUDIO, Microsoft DTV-DVD Audio Decoder, CLSID_CMPEG2AudDecoderDS

MEDIASUBTYPE_MPEG2_AUDIO, Microsoft DTV-DVD Audio Decoder, CLSID_CMPEG2AudDecoderDS

MEDIASUBTYPE_MPEG2_VIDEO, Microsoft DTV-DVD Video Decoder, CLSID_CMPEG2VidDecoderDS

{78766964-0000-0010-8000-00AA00389B71}, Mpeg4s Decoder DMO, CLSID_CMpeg4sDecMediaObject

{7634706D-0000-0010-8000-00AA00389B71}, Mpeg4s Decoder DMO, CLSID_CMpeg4sDecMediaObject

MEDIASUBTYPE_mp4s, Mpeg4s Decoder DMO, CLSID_CMpeg4sDecMediaObject

{64697678-0000-0010-8000-00AA00389B71}, Mpeg4s Decoder DMO, CLSID_CMpeg4sDecMediaObject

{58564944-0000-0010-8000-00AA00389B71}, Mpeg4s Decoder DMO, CLSID_CMpeg4sDecMediaObject

{5634504D-0000-0010-8000-00AA00389B71}, Mpeg4s Decoder DMO, CLSID_CMpeg4sDecMediaObject

MEDIASUBTYPE_MP4S, Mpeg4s Decoder DMO, CLSID_CMpeg4sDecMediaObject

MEDIASUBTYPE_WMVR, WMVideo Decoder DMO, CLSID_CWMVDecMediaObject

MEDIASUBTYPE_WMVP, WMVideo Decoder DMO, CLSID_CWMVDecMediaObject

{44495658-0000-0010-8000-00AA00389B71}, Mpeg4s Decoder DMO, CLSID_CMpeg4sDecMediaObject

MEDIASUBTYPE_WMVA, WMVideo Decoder DMO, CLSID_CWMVDecMediaObject

MEDIASUBTYPE_mpg4, Mpeg4 Decoder DMO, CLSID_CMpeg4DecMediaObject

MEDIASUBTYPE_MPG4, Mpeg4 Decoder DMO, CLSID_CMpeg4DecMediaObject
MEDIASUBTYPE_h264, Microsoft DTV-DVD Video Decoder, CLSID_CMPEG2VidDecoderDS
MEDIASUBTYPE_H264, Microsoft DTV-DVD Video Decoder, CLSID_CMPEG2VidDecoderDS
MEDIASUBTYPE_WMV3, WMVideo Decoder DMO, CLSID_CWMVDecMediaObject
MEDIASUBTYPE_mp43, Mpeg43 Decoder DMO, CLSID_CMpeg43DecMediaObject
MEDIASUBTYPE_MP43, Mpeg43 Decoder DMO, CLSID_CMpeg43DecMediaObject
MEDIASUBTYPE_m4s2, Mpeg4s Decoder DMO, CLSID_CMpeg4sDecMediaObject
MEDIASUBTYPE_WMV2, WMVideo Decoder DMO, CLSID_CWMVDecMediaObject
MEDIASUBTYPE_MSS2, WMV Screen decoder DMO, CLSID_CMSSCDecMediaObject
MEDIASUBTYPE_M4S2, Mpeg4s Decoder DMO, CLSID_CMpeg4sDecMediaObject
MEDIASUBTYPE_WVP2, WMVideo Decoder DMO, CLSID_CWMVDecMediaObject
MEDIASUBTYPE_mp42, Mpeg4 Decoder DMO, CLSID_CMpeg4DecMediaObject
MEDIASUBTYPE_MP42, Mpeg4 Decoder DMO, CLSID_CMpeg4DecMediaObject
MEDIASUBTYPE_WMV1, WMVideo Decoder DMO, CLSID_CWMVDecMediaObject
MEDIASUBTYPE_MSS1, WMV Screen decoder DMO, CLSID_CMSSCDecMediaObject
MEDIASUBTYPE_WVC1, WMVideo Decoder DMO, CLSID_CWMVDecMediaObject
MEDIASUBTYPE_AVC1, Microsoft DTV-DVD Video Decoder, CLSID_CMPEG2VidDecoderDS
MEDIASUBTYPE_MPEG_LOAS, Microsoft DTV-DVD Audio Decoder, CLSID_CMPEG2AudDecoderDS
MEDIASUBTYPE_MPEG_ADTS_AAC, Microsoft DTV-DVD Audio Decoder, CLSID_CMPEG2AudDecoderDS
MEDIASUBTYPE_WMAUDIO_LOSSLESS, WMAudio Decoder DMO, CLSID_CWMADecMediaObject
MEDIASUBTYPE_WMAUDIO3, WMAudio Decoder DMO, CLSID_CWMADecMediaObject
WMMEDIASUBTYPE_WMAudioV8, WMAudio Decoder DMO, CLSID_CWMADecMediaObject
MEDIASUBTYPE_MSAUDIO1, WMAudio Decoder DMO, CLSID_CWMADecMediaObject
MEDIASUBTYPE_RAW_AAC1, Microsoft DTV-DVD Audio Decoder, CLSID_CMPEG2AudDecoderDS
WMMEDIASUBTYPE_MP3, MP3 Decoder DMO, CLSID_CMP3DecMediaObject
MEDIASUBTYPE_MPEG1Payload, MPEG Video Decoder, CLSID_CMpegVideoCodec
MEDIASUBTYPE_MPEG1Packet, MPEG Video Decoder, CLSID_CMpegVideoCodec
{6C737664-0000-0010-8000-00AA00389B71}, DV Video Decoder, CLSID_DVVideoCodec
{64737664-0000-0010-8000-00AA00389B71}, DV Video Decoder, CLSID_DVVideoCodec
{64687664-0000-0010-8000-00AA00389B71}, DV Video Decoder, CLSID_DVVideoCodec
MEDIASUBTYPE_MJPEG, MJPEG Decompressor, CLSID_MjpegDec
{20637664-0000-0010-8000-00AA00389B71}, DV Video Decoder, CLSID_DVVideoCodec

MEDIASUBTYPE_MPEG1AudioPayload, MPEG Audio Decoder, CLSID_CMpegAudioCodec
WMMEDIASUBTYPE_WMSP2, WMSpeech Decoder DMO, CLSID_CWMSPDecMediaObject
WMMEDIASUBTYPE_WMSP1, WMSpeech Decoder DMO, CLSID_CWMSPDecMediaObject

Media Foundation File Versions

mfc core.dll, 10.00.18362.0418
mfreadwrite.dll, 10.00.18362.0001
mfcaptureengine.dll, 10.00.18362.0001
mfsensorgroup.dll, 10.00.18362.0207
windows.media.dll, 10.00.18362.0145
frameserver.dll, 10.00.18362.0207
fsclient.dll, 10.00.18362.0207

Media Foundation Transforms

[HKEY_LOCAL_MACHINE\Software\Classes\MediaFoundation\Transforms]

<category>:

<transform friendly name>, <transform CLSID>, <flags>, [<merit>,]<file name>, <file version>

Video Decoders:

AMD D3D11 Hardware MFT Playback Decoder, {17796AEB-0F66-4663-B8FB-99CBEE0224CE}, 0x4, 8, amdhwdecoder_64.dll, 26.20.13003.1007

AMD MFT MJPEG Decoder, {687CBC51-25DA-4FFC-A678-1E64943285A7}, 0x4, 8, amf-mft-mjpeg-decoder64.dll, 26.20.13003.1007

Microsoft MPEG Video Decoder MFT, {2D709E52-123F-49B5-9CBC-9AF5CDE28FB9}, 0x1, msmpeg2vdec.dll, 10.00.18362.0418

DV Decoder MFT, {404A6DE5-D4D6-4260-9BC7-5A6CBD882432}, 0x1, mfdvdec.dll, 10.00.18362.0001

Mpeg4s Decoder MFT, CLSID_CMpeg4sDecMFT, 0x1, mp4sdec.dll, 10.00.18362.0001

Microsoft H264 Video Decoder MFT, CLSID_CMSH264DecoderMFT, 0x1, msmpeg2vdec.dll, 10.00.18362.0418

WMV Screen decoder MFT, CLSID_CMSSCDecMediaObject, 0x1, wmvdec.dll, 10.00.18362.0001

WMVideo Decoder MFT, CLSID_CWMVDecMediaObject, 0x1, wmvdecod.dll, 10.00.18362.0001

MJPEG Decoder MFT, {CB17E772-E1CC-4633-8450-5617AF577905}, 0x1, mfmjpegdec.dll, 10.00.18362.0001

Mpeg43 Decoder MFT, CLSID_CMpeg43DecMediaObject, 0x1, mp43dec.dll, 10.00.18362.0001

Mpeg4 Decoder MFT, CLSID_CMpeg4DecMediaObject, 0x1, mpg4dec.dll, 10.00.18362.0001

WebpImageExtension

VP9VideoExtensionDecoder

HEIFImageExtension

Video Encoders:

AMDh265Encoder, {5FD65104-A924-4835-AB71-09A223E3E37B}, 0x4, 8, amdh265enc64.dll, 26.20.13003.1007

AMDh264Encoder, {ADC9BC80-0F41-46C6-AB75-D693D793597D}, 0x4, 8, amdh264enc64.dll, 26.20.13003.1007

H264 Encoder MFT, {6CA50344-051A-4DED-9779-A43305165E35}, 0x1, mfh264enc.dll, 10.00.18362.0001

WMVideo8 Encoder MFT, CLSID_CWMVXEncMediaObject, 0x1, wmvxenc.dll, 10.00.18362.0001

H263 Encoder MFT, {BC47FCFE-98A0-4F27-BB07-698AF24F2B38}, 0x1, mfh263enc.dll, 10.00.18362.0001

WMVideo9 Encoder MFT, CLSID_CWMV9EncMediaObject, 0x1, wmvencod.dll, 10.00.18362.0001

Microsoft MPEG-2 Video Encoder MFT, {E6335F02-80B7-4DC4-ADFA-DFE7210D20D5}, 0x2, msmpeg2enc.dll, 10.00.18362.0001

VP9VideoExtensionEncoder

HEIFImageExtension

Video Effects:

Frame Rate Converter, CLSID_CFrameRateConvertDmo, 0x1, mfvdsp.dll, 10.00.18362.0001

Resizer MFT, CLSID_CResizerDMO, 0x1, vidreszr.dll, 10.00.18362.0001

VideoStabilization MFT, {51571744-7FE4-4FF2-A498-2DC34FF74F1B}, 0x1, MSVideoDSP.dll, 10.00.18362.0001

Color Control, CLSID_CColorControlDmo, 0x1, mfvdsp.dll, 10.00.18362.0001

Color Converter MFT, CLSID_CColorConvertDMO, 0x1, colorcnv.dll, 10.00.18362.0001

Video Processor:

Microsoft Video Processor MFT, {88753B26-5B24-49BD-B2E7-0C445C78C982}, 0x1, msvproc.dll, 10.00.18362.0387

Audio Decoders:

Microsoft Dolby Digital Plus Decoder MFT, {177C0AFE-900B-48D4-9E4C-57ADD250B3D4}, 0x1, DolbyDecMFT.dll, 10.00.18362.0418

MS AMRNB Decoder MFT, {265011AE-5481-4F77-A295-ABB6FFE8D63E}, 0x1, MSAMRNBDecoder.dll, 10.00.18362.0001

WMAudio Decoder MFT, CLSID_CWMADecMediaObject, 0x1, WMADMOD.DLL, 10.00.18362.0145

Microsoft AAC Audio Decoder MFT, CLSID_CMSAACDecMFT, 0x1, MSAudDecMFT.dll, 10.00.18362.0175

A-law Wrapper MFT, {36CB6E0C-78C1-42B2-9943-846262F31786}, 0x1, mfcore.dll, 10.00.18362.0418

GSM ACM Wrapper MFT, {4A76B469-7B66-4DD4-BA2D-DDF244C766DC}, 0x1, mfcore.dll, 10.00.18362.0418

WMAPro over S/PDIF MFT, CLSID_CWMAudioSpdTxDMO, 0x1, WMADMOD.DLL, 10.00.18362.0145

Microsoft Opus Audio Decoder MFT, {63E17C10-2D43-4C42-8FE3-8D8B63E46A6A}, 0x1, MSOpusDecoder.dll, 10.00.18362.0001

Microsoft FLAC Audio Decoder MFT, {6B0B3E6B-A2C5-4514-8055-AFE8A95242D9}, 0x1, MSFlacDecoder.dll, 10.00.18362.0001

Microsoft MPEG Audio Decoder MFT, {70707B39-B2CA-4015-ABEA-F8447D22D88B}, 0x1, MSAudDecMFT.dll, 10.00.18362.0175

WMSpeech Decoder DMO, CLSID_CWMSPDDecMediaObject, 0x1, WMSPDMOD.DLL, 10.00.18362.0001

G711 Wrapper MFT, {92B66080-5E2D-449E-90C4-C41F268E5514}, 0x1, mfcore.dll, 10.00.18362.0418

IMA ADPCM ACM Wrapper MFT, {A16E1BFF-A80D-48AD-AECD-A35C005685FE}, 0x1, mfcore.dll, 10.00.18362.0418

MP3 Decoder MFT, CLSID_CMP3DecMediaObject, 0x1, mp3dmod.dll, 10.00.18362.0001

Microsoft ALAC Audio Decoder MFT, {C0CD7D12-31FC-4BBC-B363-7322EE3E1879}, 0x1, MSAlacDecoder.dll, 10.00.18362.0001

ADPCM ACM Wrapper MFT, {CA34FE0A-5722-43AD-AF23-05F7650257DD}, 0x1, mfcore.dll, 10.00.18362.0418

Dolby TrueHD IEC-61937 converter MFT, {CF5EEEDF-0E92-4B3B-A161-BD0FFE545E4B}, 0x1, mfaudiocnv.dll, 10.00.18362.0001

DTS IEC-61937 converter MFT, {D035E24C-C877-42D7-A795-2A8A339B472F}, 0x1, mfaudiocnv.dll, 10.00.18362.0001

Audio Encoders:

LPCM DVD-Audio MFT, {068A8476-9229-4CC0-9D49-2FC699DCD30A}, 0x1, mfaudiocnv.dll, 10.00.18362.0001

MP3 Encoder ACM Wrapper MFT, {11103421-354C-4CCA-A7A3-1AFF9A5B6701}, 0x1, mfcore.dll, 10.00.18362.0418

Microsoft FLAC Audio Encoder MFT, {128509E9-C44E-45DC-95E9-C255B8F466A6}, 0x1, MSFlacEncoder.dll, 10.00.18362.0001

WM Speech Encoder DMO, CLSID_CWMSPEncMediaObject2, 0x1, WMSPDMOE.DLL, 10.00.18362.0145

MS AMRNB Encoder MFT, {2FAE8AFE-04A3-423A-A814-85DB454712B0}, 0x1, MSAMRNBEncoder.dll, 10.00.18362.0001

Microsoft MPEG-2 Audio Encoder MFT, {46A4DD5C-73F8-4304-94DF-308F760974F4}, 0x1, msmpeg2enc.dll, 10.00.18362.0001

WMAudio Encoder MFT, CLSID_CWMAEncMediaObject, 0x1, WMADMOE.DLL, 10.00.18362.0145

Microsoft AAC Audio Encoder MFT, {93AF0C51-2275-45D2-A35B-F2BA21CAED00}, 0x1, mfaACEnc.dll, 10.00.18362.0001

Microsoft ALAC Audio Encoder MFT, {9AB6A28C-748E-4B6A-BFFF-CC443B8E8FB4}, 0x1, MSAlacEncoder.dll, 10.00.18362.0001

Microsoft Dolby Digital Encoder MFT, {AC3315C9-F481-45D7-826C-0B406C1F64B8}, 0x1, msac3enc.dll, 10.00.18362.0001

Audio Effects:

AEC, CLSID_CWMAudioAEC, 0x1, mfwmaaec.dll, 10.00.18362.0001

Resampler MFT, CLSID_CResamplerMediaObject, 0x1, resampledmo.dll, 10.00.18362.0001

Multiplexers:

Microsoft MPEG2 Multiplexer MFT, {AB300F71-01AB-46D2-AB6C-64906CB03258}, 0x2, mfmpeg2srcsnk.dll, 10.00.18362.0418

Others:

Microsoft H264 Video Remux (MPEG2TSToMP4) MFT, {05A47EBB-8BF0-4CBF-AD2F-3B71D75866F5}, 0x1, msmpeg2vdec.dll, 10.00.18362.0418

Media Foundation Enabled Hardware Categories

[HKEY_LOCAL_MACHINE\Software\Microsoft\Windows Media Foundation\HardwareMFT]

EnableDecoders = 1

Media Foundation Byte Stream Handlers

[HKEY_LOCAL_MACHINE\Software\Microsoft\Windows Media Foundation\ByteStreamHandlers]

[HKEY_LOCAL_MACHINE\Software\Classes\MediaFoundation\MediaSources\Preferred]

<file ext. or MIME type>, <handler CLSID>, <brief description>[, Preferred]

.3g2, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred

.3gp, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred

.3gp2, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred

.3gpp, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred

.aac, {926F41F7-003E-4382-9E84-9E953BE10562}, ADTS Byte Stream Handler, Preferred

.ac3, {46031BA1-083F-47D9-8369-23C92BDAB2FF}, AC-3 Byte Stream Handler, Preferred

.adt, {926F41F7-003E-4382-9E84-9E953BE10562}, ADTS Byte Stream Handler, Preferred

.adts, {926F41F7-003E-4382-9E84-9E953BE10562}, ADTS Byte Stream Handler, Preferred

.am?, {EFE6208A-0A2C-49FA-8A01-3768B559B6DA}, MF AMRNB Media Source ByteStreamHandler

.amr, {EFE6208A-0A2C-49FA-8A01-3768B559B6DA}, MF AMRNB Media Source ByteStreamHandler,
Preferred

.asf, {41457294-644C-4298-A28A-BD69F2C0CF3B}, ASF Byte Stream Handler, Preferred

.avi, {7AFA253E-F823-42F6-A5D9-714BDE467412}, AVI Byte Stream Handler, Preferred

.dvr-ms, {A8721937-E2FB-4D7A-A9EE-4EB08C890B6E}, MF SBE Source ByteStreamHandler

.dvr-ms, {65964407-A5D8-4060-85B0-1CCD63F768E2}, dvr-ms Byte Stream Handler, Preferred

.ec3, {46031BA1-083F-47D9-8369-23C92BDAB2FF}, AC-3 Byte Stream Handler, Preferred

.flac, {0E41CFB8-0506-40F4-A516-77CC23642D91}, MF FLAC Media Source ByteStreamHandler, Preferred

.m2t, {40871C59-AB40-471F-8DC3-1F259D862479}, MPEG2 Byte Stream Handler, Preferred

.m2ts, {40871C59-AB40-471F-8DC3-1F259D862479}, MPEG2 Byte Stream Handler, Preferred

.m4a, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred

.m4v, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred
.mk3d, {1F9A2C18-D89E-463E-B4F4-BB90152ACC64}, MKV Byte Stream Handler, Preferred
.mka, {1F9A2C18-D89E-463E-B4F4-BB90152ACC64}, MKV Byte Stream Handler, Preferred
.mks, {1F9A2C18-D89E-463E-B4F4-BB90152ACC64}, MKV Byte Stream Handler, Preferred
.mkv, {1F9A2C18-D89E-463E-B4F4-BB90152ACC64}, MKV Byte Stream Handler, Preferred
.mod, {40871C59-AB40-471F-8DC3-1F259D862479}, MPEG2 Byte Stream Handler, Preferred
.mov, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred
.mp2v, {40871C59-AB40-471F-8DC3-1F259D862479}, MPEG2 Byte Stream Handler, Preferred
.mp3, {A82E50BA-8E92-41EB-9DF2-433F50EC2993}, MP3 Byte Stream Handler, Preferred
.mp4, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred
.mp4v, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred
.mpa, {A82E50BA-8E92-41EB-9DF2-433F50EC2993}, MP3 Byte Stream Handler, Preferred
.mpeg, {40871C59-AB40-471F-8DC3-1F259D862479}, MPEG2 Byte Stream Handler, Preferred
.mpg, {40871C59-AB40-471F-8DC3-1F259D862479}, MPEG2 Byte Stream Handler, Preferred
.mts, {40871C59-AB40-471F-8DC3-1F259D862479}, MPEG2 Byte Stream Handler, Preferred
.nsc, {B084785C-DDE0-4D30-8CA8-05A373E185BE}, NSC Byte Stream Handler, Preferred
.sami, {7A56C4CB-D678-4188-85A8-BA2EF68FA10D}, SAMI Byte Stream Handler, Preferred
.smi, {7A56C4CB-D678-4188-85A8-BA2EF68FA10D}, SAMI Byte Stream Handler, Preferred
.tod, {40871C59-AB40-471F-8DC3-1F259D862479}, MPEG2 Byte Stream Handler, Preferred
.ts, {40871C59-AB40-471F-8DC3-1F259D862479}, MPEG2 Byte Stream Handler, Preferred
.tts, {40871C59-AB40-471F-8DC3-1F259D862479}, MPEG2 Byte Stream Handler, Preferred
.uvu, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred
.vob, {40871C59-AB40-471F-8DC3-1F259D862479}, MPEG2 Byte Stream Handler, Preferred
.wav, {42C9B9F5-16FC-47EF-AF22-DA05F7C842E3}, WAV Byte Stream Handler, Preferred
.weba, {1F9A2C18-D89E-463E-B4F4-BB90152ACC64}, WEBM Byte Stream Handler, Preferred
.webm, {1F9A2C18-D89E-463E-B4F4-BB90152ACC64}, WEBM Byte Stream Handler, Preferred
.wm, {41457294-644C-4298-A28A-BD69F2C0CF3B}, ASF Byte Stream Handler, Preferred
.wma, {41457294-644C-4298-A28A-BD69F2C0CF3B}, ASF Byte Stream Handler, Preferred
.wmv, {41457294-644C-4298-A28A-BD69F2C0CF3B}, ASF Byte Stream Handler, Preferred
.wtv, {65964407-A5D8-4060-85B0-1CCD63F768E2}, WTV Byte Stream Handler, Preferred
audio/3gpp, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred
audio/3gpp2, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred

audio/aac, {926F41F7-003E-4382-9E84-9E953BE10562}, ADTS Byte Stream Handler, Preferred

audio/aacp, {926F41F7-003E-4382-9E84-9E953BE10562}, ADTS Byte Stream Handler, Preferred

audio/eac3, {46031BA1-083F-47D9-8369-23C92BDAB2FF}, AC-3 Byte Stream Handler, Preferred

audio/flac, {0E41CFB8-0506-40F4-A516-77CC23642D91}, MF FLAC Media Source ByteStreamHandler, Preferred

audio/L16, {3FFB3B8C-EB99-472B-8902-E1C1B05F07CF}, LPCM Byte Stream Handler, Preferred

audio/mp3, {A82E50BA-8E92-41EB-9DF2-433F50EC2993}, MP3 Byte Stream Handler, Preferred

audio/mp4, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred

audio/MP4A-LATM, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred

audio/mpa, {A82E50BA-8E92-41EB-9DF2-433F50EC2993}, MP3 Byte Stream Handler, Preferred

audio/mpeg, {A82E50BA-8E92-41EB-9DF2-433F50EC2993}, MP3 Byte Stream Handler, Preferred

audio/mpeg3, {A82E50BA-8E92-41EB-9DF2-433F50EC2993}, MP3 Byte Stream Handler, Preferred

audio/vnd.dlna.adts, {926F41F7-003E-4382-9E84-9E953BE10562}, ADTS Byte Stream Handler, Preferred

audio/vnd.dolby.dd-raw, {46031BA1-083F-47D9-8369-23C92BDAB2FF}, AC-3 Byte Stream Handler, Preferred

audio/wav, {42C9B9F5-16FC-47EF-AF22-DA05F7C842E3}, WAV Byte Stream Handler, Preferred

audio/webm, {1F9A2C18-D89E-463E-B4F4-BB90152ACC64}, WEBM Byte Stream Handler, Preferred

audio/x-aac, {926F41F7-003E-4382-9E84-9E953BE10562}, ADTS Byte Stream Handler, Preferred

audio/x-flac, {0E41CFB8-0506-40F4-A516-77CC23642D91}, MF FLAC Media Source ByteStreamHandler, Preferred

audio/x-m4a, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred

audio/x-matroska, {1F9A2C18-D89E-463E-B4F4-BB90152ACC64}, MKV Byte Stream Handler, Preferred

audio/x-mp3, {A82E50BA-8E92-41EB-9DF2-433F50EC2993}, MP3 Byte Stream Handler, Preferred

audio/x-mpeg, {A82E50BA-8E92-41EB-9DF2-433F50EC2993}, MP3 Byte Stream Handler, Preferred

audio/x-ms-wma, {41457294-644C-4298-A28A-BD69F2C0CF3B}, ASF Byte Stream Handler, Preferred

audio/x-wav, {42C9B9F5-16FC-47EF-AF22-DA05F7C842E3}, WAV Byte Stream Handler, Preferred

video/3gpp, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred

video/3gpp2, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred

video/avi, {7AFA253E-F823-42F6-A5D9-714BDE467412}, AVI Byte Stream Handler, Preferred

video/mp4, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred

video/mpeg, {40871C59-AB40-471F-8DC3-1F259D862479}, MPEG2 Byte Stream Handler, Preferred

video/msvideo, {7AFA253E-F823-42F6-A5D9-714BDE467412}, AVI Byte Stream Handler, Preferred

video/vnd.dece.mp4, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred

video/vnd.dlna.mpeg-tts, {40871C59-AB40-471F-8DC3-1F259D862479}, MPEG2 Byte Stream Handler, Preferred

video/webm, {1F9A2C18-D89E-463E-B4F4-BB90152ACC64}, WEBM Byte Stream Handler, Preferred

video/x-m4v, {271C3902-6095-4C45-A22F-20091816EE9E}, MPEG4 Byte Stream Handler, Preferred

video/x-matroska, {1F9A2C18-D89E-463E-B4F4-BB90152ACC64}, MKV Byte Stream Handler, Preferred

video/x-ms-asf, {41457294-644C-4298-A28A-BD69F2C0CF3B}, ASF Byte Stream Handler, Preferred

video/x-ms-wm, {41457294-644C-4298-A28A-BD69F2C0CF3B}, ASF Byte Stream Handler, Preferred

video/x-ms-wmv, {41457294-644C-4298-A28A-BD69F2C0CF3B}, ASF Byte Stream Handler, Preferred

video/x-msvideo, {7AFA253E-F823-42F6-A5D9-714BDE467412}, AVI Byte Stream Handler, Preferred

Media Foundation Scheme Handlers

[HKEY_LOCAL_MACHINE\Software\Microsoft\Windows Media Foundation\SchemaHandlers]

[HKEY_LOCAL_MACHINE\Software\Classes\MediaFoundation\MediaSources\Preferred]

<URL type>, <handler CLSID>, <brief description>[, Preferred]

file:, {477EC299-1421-4BDD-971F-7CCB933F21AD}, File Scheme Handler, Preferred

http:, {44CB442B-9DA9-49DF-B3FD-023777B16E50}, Http Scheme Handler

http:, {9EC4B4F9-3029-45AD-947B-344DE2A249E2}, Urlmon Scheme Handler

http:, {E9F4EBAB-D97B-463E-A2B1-C54EE3F9414D}, Net Scheme Handler, Preferred

httpd:, {44CB442B-9DA9-49DF-B3FD-023777B16E50}, Http Scheme Handler, Preferred

https:, {37A61C8B-7F8E-4D08-B12B-248D73E9AB4F}, Secure Http Scheme Handler, Preferred

httpsd:, {37A61C8B-7F8E-4D08-B12B-248D73E9AB4F}, Secure Http Scheme Handler, Preferred

http:, {E9F4EBAB-D97B-463E-A2B1-C54EE3F9414D}, Net Scheme Handler, Preferred

httpu:, {E9F4EBAB-D97B-463E-A2B1-C54EE3F9414D}, Net Scheme Handler, Preferred

mcast:, {E9F4EBAB-D97B-463E-A2B1-C54EE3F9414D}, Net Scheme Handler, Preferred

mcrecv:, {FA6D33D4-9405-4BA5-9983-12604AC8E77A}, Miracast Sink Scheme Handler, Preferred

mms:, {E9F4EBAB-D97B-463E-A2B1-C54EE3F9414D}, Net Scheme Handler, Preferred

ms-appdata:, {CFC81939-3886-4ACF-9692-DA58037AE716}, MsAppData Scheme Handler, Preferred
ms-appx-web:, {8DB0224B-3D65-4F6F-8E12-BEB4B78B8974}, MsAppxWeb Scheme Handler, Preferred
ms-appx:, {8DB0224B-3D65-4F6F-8E12-BEB4B78B8974}, MsAppx Scheme Handler, Preferred
ms-winsoundevent:, {F79A6BF9-7415-4CF3-AE10-4559509ABC3C}, Sound Event Scheme Handler, Preferred
rtsp:, {E9F4EBAB-D97B-463E-A2B1-C54EE3F9414D}, Net Scheme Handler, Preferred
rtsp:, {E9F4EBAB-D97B-463E-A2B1-C54EE3F9414D}, Net Scheme Handler, Preferred
rtsp:, {E9F4EBAB-D97B-463E-A2B1-C54EE3F9414D}, Net Scheme Handler, Preferred
rtsp:, {E9F4EBAB-D97B-463E-A2B1-C54EE3F9414D}, Net Scheme Handler, Preferred
rtsp:, {E9F4EBAB-D97B-463E-A2B1-C54EE3F9414D}, Net Scheme Handler, Preferred
rtsp:, {E9F4EBAB-D97B-463E-A2B1-C54EE3F9414D}, Net Scheme Handler, Preferred

Preferred Media Foundation Transforms

[HKEY_LOCAL_MACHINE\Software\Classes\MediaFoundation\Transforms\Preferred]

<media subtype GUID>, [<transform friendly name>,]<transform CLSID>

{EB27CEC4-163E-4CA3-8B74-8E25F91B517E}, Dolby TrueHD IEC-61937 converter MFT, {CF5EEEDF-0E92-4B3B-A161-BD0FFE545E4B}

{E06D802C-DB46-11CF-B4D1-00805F6CBBEA}, Microsoft Dolby Digital Plus Decoder MFT, {177C0AFE-900B-48D4-9E4C-57ADD250B3D4}

MFVideoFormat_MPEG2, Microsoft MPEG Video Decoder MFT, {2D709E52-123F-49B5-9CBC-9AF5CDE28FB9}

MEDIASUBTYPE_DOLBY_DDPLUS, Microsoft Dolby Digital Plus Decoder MFT, {177C0AFE-900B-48D4-9E4C-57ADD250B3D4}

{A61AC364-AD0E-4744-89FF-213CE0DF8804}, DTS IEC-61937 converter MFT, {D035E24C-C877-42D7-A795-2A8A339B472F}

{A2E58EB7-0FA9-48BB-A40C-FA0E156D0645}, DTS IEC-61937 converter MFT, {D035E24C-C877-42D7-A795-2A8A339B472F}

{7634706D-0000-0010-8000-00AA00389B71}, Mpeg4s Decoder MFT, CLSID_CMpeg4sDecMFT

{73616D72-767A-494D-B478-F29D25DC9037}, MS AMRNB Decoder MFT, {265011AE-5481-4F77-A295-ABB6FFE8D63E}

MEDIASUBTYPE_mp4s, Mpeg4s Decoder MFT, CLSID_CMpeg4sDecMFT

MFVideoFormat_DVSL, DV Decoder MFT, {404A6DE5-D4D6-4260-9BC7-5A6CBD882432}

MFVideoFormat_DVSD, DV Decoder MFT, {404A6DE5-D4D6-4260-9BC7-5A6CBD882432}

MFVideoFormat_DVHD, DV Decoder MFT, {404A6DE5-D4D6-4260-9BC7-5A6CBD882432}

{63616C61-0000-0010-8000-00AA00389B71}, Microsoft ALAC Audio Decoder MFT, {C0CD7D12-31FC-4BBC-B363-7322EE3E1879}

MFVideoFormat_MP4V, Mpeg4s Decoder MFT, CLSID_CMpeg4sDecMFT

MFVideoFormat_MP4S, Mpeg4s Decoder MFT, CLSID_CMpeg4sDecMFT

{53314356-0000-0010-8000-00AA00389B71}, WMVideo Decoder MFT, CLSID_CWMVDecMediaObject

MEDIASUBTYPE_WMVR, WMVideo Decoder MFT, CLSID_CWMVDecMediaObject

MEDIASUBTYPE_WMVP, WMVideo Decoder MFT, CLSID_CWMVDecMediaObject

MFVideoFormat_MJPG, MJPEG Decoder MFT, {CB17E772-E1CC-4633-8450-5617AF577905}

MEDIASUBTYPE_WMVA, WMVideo Decoder MFT, CLSID_CWMVDecMediaObject

{3F40F4F0-5622-4FF8-B6D8-A17A584BEE5E}, Microsoft H264 Video Decoder MFT, CLSID_CMSH264DecoderMFT

MEDIASUBTYPE_mpg4, Mpeg4 Decoder MFT, CLSID_CMpeg4DecMediaObject

MEDIASUBTYPE_MPG4, Mpeg4 Decoder MFT, CLSID_CMpeg4DecMediaObject

MFVideoFormat_H264, Microsoft H264 Video Decoder MFT, CLSID_CMSH264DecoderMFT

MFVideoFormat_WMV3, WMVideo Decoder MFT, CLSID_CWMVDecMediaObject

{33363248-0000-0010-8000-00AA00389B71}, Mpeg4s Decoder MFT, CLSID_CMpeg4sDecMFT

MEDIASUBTYPE_mp43, Mpeg43 Decoder MFT, CLSID_CMpeg43DecMediaObject

MFVideoFormat_MP43, Mpeg43 Decoder MFT, CLSID_CMpeg43DecMediaObject

MEDIASUBTYPE_m4s2, Mpeg4s Decoder MFT, CLSID_CMpeg4sDecMFT

MFVideoFormat_WMV2, WMVideo Decoder MFT, CLSID_CWMVDecMediaObject

MFVideoFormat_MSS2, WMV Screen decoder MFT, CLSID_CMSSCDecMediaObject

MFVideoFormat_M4S2, Mpeg4s Decoder MFT, CLSID_CMpeg4sDecMFT

MEDIASUBTYPE_WVP2, WMVideo Decoder MFT, CLSID_CWMVDecMediaObject

MEDIASUBTYPE_mp42, Mpeg4 Decoder MFT, CLSID_CMpeg4DecMediaObject

MEDIASUBTYPE_MP42, Mpeg4 Decoder MFT, CLSID_CMpeg4DecMediaObject

MFVideoFormat_WMV1, WMVideo Decoder MFT, CLSID_CWMVDecMediaObject

MFVideoFormat_MSS1, WMV Screen decoder MFT, CLSID_CMSSCDecMediaObject

MFVideoFormat_MPG1, Microsoft MPEG Video Decoder MFT, {2D709E52-123F-49B5-9CBC-9AF5CDE28FB9}

MFVideoFormat_WVC1, WMVideo Decoder MFT, CLSID_CWMVDecMediaObject

MFVideoFormat_DVC, DV Decoder MFT, {404A6DE5-D4D6-4260-9BC7-5A6CBD882432}

{0000F1AC-0000-0010-8000-00AA00389B71}, Microsoft FLAC Audio Decoder MFT, {6B0B3E6B-A2C5-4514-8055-AFE8A95242D9}

{00007361-0000-0010-8000-00AA00389B71}, MS AMRNB Decoder MFT, {265011AE-5481-4F77-A295-ABB6FFE8D63E}

{0000704F-0000-0010-8000-00AA00389B71}, Microsoft Opus Audio Decoder MFT, {63E17C10-2D43-4C42-8FE3-8D8B63E46A6A}

{00006C61-0000-0010-8000-00AA00389B71}, Microsoft ALAC Audio Decoder MFT, {COCD7D12-31FC-4BBC-B363-7322EE3E1879}

{00002001-0000-0010-8000-00AA00389B71}, DTS IEC-61937 converter MFT, {D035E24C-C877-42D7-A795-2A8A339B472F}

{00002000-0000-0010-8000-00AA00389B71}, Microsoft Dolby Digital Plus Decoder MFT, {177C0AFE-900B-48D4-9E4C-57ADD250B3D4}

MFAudioFormat_AAC, Microsoft AAC Audio Decoder MFT, CLSID_CMSAACDecMFT

MFAudioFormat_ADTS, Microsoft AAC Audio Decoder MFT, CLSID_CMSAACDecMFT

MFAudioFormat_WMAudio_Lossless, WMAudio Decoder MFT, CLSID_CWMADecMediaObject

MFAudioFormat_WMAudioV9, WMAudio Decoder MFT, CLSID_CWMADecMediaObject

MFAudioFormat_WMAudioV8, WMAudio Decoder MFT, CLSID_CWMADecMediaObject

MEDIASUBTYPE_MSAUDIO1, WMAudio Decoder MFT, CLSID_CWMADecMediaObject

MEDIASUBTYPE_RAW_AAC1, Microsoft AAC Audio Decoder MFT, CLSID_CMSAACDecMFT

MFAudioFormat_MP3, MP3 Decoder MFT, CLSID_CMP3DecMediaObject

MFAudioFormat_MPEG, Microsoft MPEG Audio Decoder MFT, {70707B39-B2CA-4015-ABEA-F8447D22D88B}

{00000031-0000-0010-8000-00AA00389B71}, GSM ACM Wrapper MFT, {4A76B469-7B66-4DD4-BA2D-DDF244C766DC}

{00000011-0000-0010-8000-00AA00389B71}, IMA ADPCM ACM Wrapper MFT, {A16E1BFF-A80D-48AD-AECD-A35C005685FE}

KSDATAFORMAT_SUBTYPE_MULAW, G711 Wrapper MFT, {92B66080-5E2D-449E-90C4-C41F268E5514}

{00000006-0000-0010-8000-00AA00389B71}, A-law Wrapper MFT, {36CB6E0C-78C1-42B2-9943-846262F31786}

KSDATAFORMAT_SUBTYPE_ADPCM, ADPCM ACM Wrapper MFT, {CA34FE0A-5722-43AD-AF23-05F7650257DD}

WMEDIASUBTYPE_WMSP2, WMSpeech Decoder DMO, CLSID_CWMSPDecMediaObject

MFAudioFormat_MSP1, WMSpeech Decoder DMO, CLSID_CWMSPDecMediaObject

Disabled Media Foundation Transforms

[HKEY_LOCAL_MACHINE\Software\Classes\MediaFoundation\Transforms\DoNotUse]

<transform CLSID>

Disabled Media Sources

[HKEY_LOCAL_MACHINE\Software\Classes\MediaFoundation\MediaSources\DoNotUse]

<media source CLSID>

EVR Power Information

Current Setting: {5C67A112-A4C9-483F-B4A7-1D473BECAFDC} (Quality)

Quality Flags: 2576

Enabled:

Force throttling

Allow half deinterlace

Allow scaling

Decode Power Usage: 100

Balanced Flags: 1424

Enabled:

Force throttling

Allow batching

Force half deinterlace

Force scaling

Decode Power Usage: 50

PowerFlags: 1424

Enabled:

Force throttling

Allow batching

Force half deinterlace

Force scaling

Decode Power Usage: 0

Diagnostics

Windows Error Reporting:

+++ WERO +++:

Bucket errato 1922379340068476368, tipo 5

Nome evento: RADAR_PRE_LEAK_64

Risposta: Non disponibile

ID CAB: 0

Firma problema:

P1: DarkSoulsIII.exe

P2: 1.15.0.0

P3: 10.0.18362.2.0.0

P4:

P5:

P6:

P7:

P8:

P9:

P10:

File allegati:

\\?\C:\Users\fr_ag\AppData\Local\Temp\RDR5214.tmp\empty.txt

\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER5215.tmp.WERInternalMetadata.xml

\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER5226.tmp.xml

\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER5243.tmp.csv

\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER5263.tmp.txt

I file potrebbero essere disponibili qui:

Simbolo analisi:

Nuova ricerca di soluzioni: 0

ID rapporto: 06b1851d-4d75-4cb5-9ffe-3c716fba5a16

Stato rapporto: 268435456

Bucket con hash: ec922f47e66a8f534aada9d31854d5d0

GUID CAB: 0

+++ WER1 +++:

Bucket errato 1269816605860194184, tipo 1

Nome evento: APPCRASH

Risposta: Non disponibile

ID CAB: 0

Firma problema:

P1: ArmourySwAgent.exe

P2: 1.0.0.2

P3: 5d5bad2c

P4: KERNELBASE.dll

P5: 10.0.18362.418

P6: 2b181c2c

P7: c000041d

P8: 00113572

P9:

P10:

File allegati:

\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER5E0B.tmp.dmp

\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER5E5A.tmp.WERInternalMetadata.xml

\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER5E6B.tmp.xml

\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER5E7B.tmp.csv

\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER5E8B.tmp.txt

I file potrebbero essere disponibili qui:

\\?\C:\ProgramData\Microsoft\Windows\WER\ReportArchive\AppCrash_ArmourySwAgent.e_5bc6e23fa2f063fefe1228eb6518ed359f351af9_eafe6a60_3d292968-3edc-4660-8fd2-c148f2311e7d

Simbolo analisi:

Nuova ricerca di soluzioni: 0

ID rapporto: ffe472e0-e4e1-4980-94e3-a4e0fa02f9a8

Stato rapporto: 268435456

Bucket con hash: 2913d965cb00cb4cb19f4b79aa306788

GUID CAB: 0

+++ WER2 +++:

Bucket errato 2018650955572005702, tipo 1

Nome evento: APPCRASH

Risposta: Non disponibile

ID CAB: 0

Firma problema:

P1: ArmourySwAgent.exe

P2: 1.0.0.2

P3: 5d5bad2c

P4: KERNELBASE.dll

P5: 10.0.18362.418

P6: 2b181c2c

P7: c0020001

P8: 00113572

P9:

P10:

File allegati:

\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER5735.tmp.dmp

\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER57C3.tmp.WERInternalMetadata.xml

\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER57D3.tmp.xml

\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER57D1.tmp.csv

\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER57F2.tmp.txt

I file potrebbero essere disponibili qui:

\\?\C:\ProgramData\Microsoft\Windows\WER\ReportArchive\AppCrash_ArmourySwAgent.e_ba9c8b174824543e413175af9eb4eae281f7_eafe6a60_34638300-7846-4668-9bfe-b246eba1d9cc

Simbolo analisi:

Nuova ricerca di soluzioni: 0

ID rapporto: 5593aaad-b01e-4586-b2e0-912e2f1c1237

Stato rapporto: 268435456

Bucket con hash: bb8a5ca452480cc67c03b0594c5f4b46

GUID CAB: 0

+++ WER3 +++:

Bucket errato 1642562886851998255, tipo 1

Nome evento: APPCRASH

Risposta: Non disponibile

ID CAB: 0

Firma problema:

P1: LightingService.exe

P2: 0.0.0.0

P3: 5d79ead6

P4: LightingService.exe

P5: 0.0.0.0

P6: 5d79ead6

P7: c0000005

P8: 00093cf9

P9:

P10:

File allegati:

\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER2C11.tmp.dmp

\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER2DB8.tmp.WERInternalMetadata.xml

\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER2DD8.tmp.xml

\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER2DD6.tmp.csv

\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WER2DF6.tmp.txt

I file potrebbero essere disponibili qui:

\\?\C:\ProgramData\Microsoft\Windows\WER\ReportArchive\AppCrash_LightingService._dc4ce594ec2a8785dca0bc26de8b4a1e58952e63_cb106220_29c55969-2307-49af-b633-eb108b134f2a

Simbolo analisi:

Nuova ricerca di soluzioni: 0

ID rapporto: 5a7990fa-6f3f-4f2c-bd5a-0788293064a5

Stato rapporto: 268435456

Bucket con hash: 06d14b3c5562263e16cb8e3e300db22f

GUID CAB: 0

+++ WER4 +++:

Bucket errato 1198791466333484706, tipo 5

Nome evento: StoreAgentScanForUpdatesFailure0

Risposta: Non disponibile

ID CAB: 0

Firma problema:

P1: Update;

P2: 8024402c

P3: 18362

P4: 418

P5: Windows.Desktop

P6:

P7:

P8:

P9:

P10:

File allegati:

\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WERFBBB.tmp.WERInternalMetadata.xml

I file potrebbero essere disponibili qui:

\\?\C:\ProgramData\Microsoft\Windows\WER\ReportArchive\NonCritical_Update;_9bf0f9a2eeea3a243f81b8d54c864b9e28f9062_00000000_b6a2d2bc-d621-4a0a-8a84-5ccd74125be8

Simbolo analisi:

Nuova ricerca di soluzioni: 0

ID rapporto: b6a2d2bc-d621-4a0a-8a84-5ccd74125be8

Stato rapporto: 268435556

Bucket con hash: 27a8aeffb72d1e2770a2f67cb693b6a2

GUID CAB: 0

+++ WER5 +++:

Bucket errato 1768664720558155865, tipo 5

Nome evento: BEX64

Risposta: Non disponibile

ID CAB: 0

Firma problema:

P1: atiesrxx.exe

P2: 26.20.11016.1

P3: 5cdb43f4

P4: StackHash_ac46

P5: 0.0.0.0

P6: 00000000

P7: PCH_DO_FROM_ntdll+0x000000000009CC14

P8: c0000005

P9: 0000000000000008

P10:

File allegati:

\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WERE276.tmp.WERInternalMetadata.xml

I file potrebbero essere disponibili qui:

\\?\C:\ProgramData\Microsoft\Windows\WER\ReportArchive\AppCrash_atiesrxx.exe_f78695c9de1e8bb3d1bb66d3a3fa0e622aea677_ad79e2ad_cd4a4c07-b914-49e0-93cd-4b7374f0dd18

Simbolo analisi:

Nuova ricerca di soluzioni: 0

ID rapporto: 1d3b3318-6540-4b2d-8413-b5fd5f3457fa

Stato rapporto: 268435556

Bucket con hash: ed23ffd62d170264988b8f314ba26859

GUID CAB: 0

+++ WER6 +++:

Bucket errato , tipo 0

Nome evento: StoreAgentScanForUpdatesFailure0

Risposta: Non disponibile

ID CAB: 0

Firma problema:

P1: Update;

P2: 8024402c

P3: 18362

P4: 418

P5: Windows.Desktop

P6:

P7:

P8:

P9:

P10:

File allegati:

\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WERFBBB.tmp.WERInternalMetadata.xml

I file potrebbero essere disponibili qui:

\\?\C:\ProgramData\Microsoft\Windows\WER\ReportQueue\NonCritical_Update;_9bf0f9a2eeea3a243f81b8d54c864b9e28f9062_00000000_b6a2d2bc-d621-4a0a-8a84-5ccd74125be8

Simbolo analisi:

Nuova ricerca di soluzioni: 0

ID rapporto: b6a2d2bc-d621-4a0a-8a84-5ccd74125be8

Stato rapporto: 100

Bucket con hash:

GUID CAB: 0

+++ WER7 +++:

Bucket errato , tipo 0

Nome evento: BEX64

Risposta: Non disponibile

ID CAB: 0

Firma problema:

P1: atiesrxx.exe

P2: 26.20.11016.1

P3: 5cdb43f4

P4: StackHash_ac46

P5: 0.0.0.0

P6: 00000000

P7: PCH_D0_FROM_ntdll+0x000000000009CC14

P8: c0000005

P9: 0000000000000008

P10:

File allegati:

\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WERE276.tmp.WERInternalMetadata.xml

I file potrebbero essere disponibili qui:

\\?\C:\ProgramData\Microsoft\Windows\WER\ReportQueue\AppCrash_atiesrxx.exe_f78695c9de1e8bb3d1bb66d3a3fa0e622aea677_ad79e2ad_cd4a4c07-b914-49e0-93cd-4b7374f0dd18

Simbolo analisi:

Nuova ricerca di soluzioni: 0

ID rapporto: 1d3b3318-6540-4b2d-8413-b5fd5f3457fa

Stato rapporto: 100

Bucket con hash:

GUID CAB: 0

+++ WER8 +++:

Bucket errato , tipo 0

Nome evento: StoreAgentScanForUpdatesFailure0

Risposta: Non disponibile

ID CAB: 0

Firma problema:

P1: Update;

P2: 8024402c

P3: 18362

P4: 418

P5: Windows.Desktop

P6:

P7:

P8:

P9:

P10:

File allegati:

I file potrebbero essere disponibili qui:

\\?\C:\ProgramData\Microsoft\Windows\WER\ReportQueue\NonCritical_Update;_9bf0f9a2eeea3a243f81b8d54c864b9e28f9062_00000000_b6a2d2bc-d621-4a0a-8a84-5ccd74125be8

Simbolo analisi:

Nuova ricerca di soluzioni: 0

ID rapporto: b6a2d2bc-d621-4a0a-8a84-5ccd74125be8

Stato rapporto: 4

Bucket con hash:

GUID CAB: 0

+++ WER9 +++:

Bucket errato , tipo 0

Nome evento: BEX64

Risposta: Non disponibile

ID CAB: 0

Firma problema:

P1: atiesrxx.exe

P2: 26.20.11016.1

P3: 5cdb43f4

P4: StackHash_ac46

P5: 0.0.0.0

P6: 00000000

P7: PCH_DO_FROM_ntdll+0x000000000009CC14

P8: c0000005

P9: 0000000000000008

P10:

File allegati:

\\?\C:\ProgramData\Microsoft\Windows\WER\Temp\WERE276.tmp.WERInternalMetadata.xml

I file potrebbero essere disponibili qui:

\\?\C:\ProgramData\Microsoft\Windows\WER\ReportQueue\AppCrash_atiesrxx.exe_f78695c9de1e8bb3d1bb66d3a3fa0e622aea677_ad79e2ad_cd4a4c07-b914-49e0-93cd-4b7374f0dd18

Simbolo analisi:

Nuova ricerca di soluzioni: 0

ID rapporto: 1d3b3318-6540-4b2d-8413-b5fd5f3457fa

Stato rapporto: 100

Bucket con hash:

GUID CAB: 0